


Index No. T-U 25

CASS COUNTY LAND CORNER RECORD

T. 144 R. 28 M. 5th Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
MC # 8 Corner common to sections 25 AND 30 - 144-27



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1873  
Original monument Post

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees

Species	<u>Tam</u>	<u>Tam</u>	_____	_____
Diameter	<u>10"</u>	<u>7"</u>	_____	_____
Bearing	<u>South</u>	<u>S31W</u>	_____	_____
Distance	<u>47Ls</u>	<u>33Ls</u>	_____	_____

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1937 By GLO  
Location filed Sec. of State  
Monument End both BITS set past in bog - also set 1x36" IR. w/brass cap 0.30 ch. South WC MC

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_

Bearing Trees, Reference Objects

Species	<u>Tam</u>	<u>Cedar</u>	_____	_____
Diameter	<u>5"</u>	<u>10"</u>	_____	_____
Bearing	<u>S57<sup>3</sup>/<sub>4</sub>E</u>	<u>S81W</u>	_____	_____
Distance	<u>34Ls</u>	<u>12Ls</u>	_____	_____

BITS TO IRON

Bearing Trees, Reference Objects

_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_