


Index No. 113

CASS COUNTY LAND CORNER RECORD

T. 144 R. 28 M. 5th Coordinates: X _____ Y _____
NE 33 Corner common to sections 27, 28, 33, 34



EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species NO trees
Diameter _____
Bearing _____
Distance _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed 1915 By E. B. Horst
Location filed County Book C P 277
Monument SET 6" x 6" x 12' CEDAR POST PROPORTIONALLY
in lake 3' out of water
also on microfilm roll 115 BK 71 P 37

Evidence of Subsequent Corner Restoration

Year of search _____ By _____
Co DITCH SURVEY BK 172 BOX 3 OF Co.
DITCH SURVEY BOOKS PG 78

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____