


Index No. V 14

CASS COUNTY LAND CORNER RECORD

T. 144 R. 28 M. 5th Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
W 116 Corner common to sections 27, 24



EXISTING SURVEYS

**Original Government Survey**

Year surveyed \_\_\_\_\_  
Original monument \_\_\_\_\_

**Bearing Trees**

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

**Original Evidence Found**

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

**Original Bearing Trees Found**

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

**Subsequent Corner Restoration**

Year surveyed 1964 By Co Hwy Dept  
Location filed Co Rd # 8  
Monument Found brass cap monument

**Evidence of Subsequent Corner Restoration**

Year of search \_\_\_\_\_ By \_\_\_\_\_

**Bearing Trees, Reference Objects**

Species	<u>Poplar</u>	<u>ELM</u>	<u>Poplar</u>
Diameter	<u>8"</u>	<u>6"</u>	<u>8"</u>
Bearing	<u>NE</u>	<u>SE</u>	<u>E</u>
Distance	<u>77.3'</u>	<u>66.1'</u>	<u>66.3'</u>

**Bearing Trees, Reference Objects**

**Subsequent Corner Restoration**

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

**Evidence of Subsequent Corner Restoration Found**

Year of search \_\_\_\_\_ By \_\_\_\_\_

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_