


Index No. V17

CASS COUNTY LAND CORNER RECORD

T. 144 R. 28 M. 5th Coordinates: X _____ Y _____
NE 34 Corner common to sections 26, 27, 34, 35



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species	<u>Tam</u>	<u>Tam</u>	<u>Tam</u>	<u>Tam</u>
Diameter	<u>4"</u>	<u>3"</u>	<u>3"</u>	<u>3"</u>
Bearing	<u>S31E</u>	<u>S40 1/2 W</u>	<u>N70W</u>	<u>N20 1/2 W</u>
Distance	<u>19LKS</u>	<u>27LKS</u>	<u>18LKS</u>	<u>36LKS</u>

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1915 By E. B. Horst
Location filed County Book 'C' P. 276
Monument Set Hub. Set 2 1/4 x 4 1/8" I.M.

Evidence of Subsequent Corner Restoration

Year of search _____ By _____
Co. DITCH SURVEY BK 172. BOX 3 of Co.
DITCH SURVEY BOOKS PG 3 + BK 172
PG 78

also on microfilm - roll 115 BK 71 P. 24-25
P. 64 set 2 1/4 x 4 1/8" I.M.

Bearing Trees, Reference Objects

Species	<u>TAM</u>	<u>TAM</u>	<u>TAM</u>	<u>TAM</u>
Diameter	<u>10"</u>	<u>10"</u>	<u>5"</u>	<u>6"</u>
Bearing	<u>S59-30E</u>	<u>N47-30E</u>	<u>S37-45W</u>	<u>N41-30W</u>
Distance	<u>64.20'</u>	<u>32.80'</u>	<u>35.00'</u>	<u>57.70'</u>

Bearing Trees, Reference Objects

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

to head of 2nd nail in base of tree

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____