


Index No. V 23

CASS COUNTY LAND CORNER RECORD

T. 144 R. 28 M. 5th Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
N 1/4 36 Corner common to sections 25, 36



EXISTING SURVEYS

Original Government Survey

Year surveyed 1873  
Original monument Post

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

|          | Bearing Trees |               |
|----------|---------------|---------------|
| Species  | <u>Tam</u>    | <u>Tam</u>    |
| Diameter | <u>5"</u>     | <u>4"</u>     |
| Bearing  | <u>S 37 W</u> | <u>N 10 E</u> |
| Distance | <u>22 LKS</u> | <u>16 LKS</u> |

| Original Bearing Trees Found |       |
|------------------------------|-------|
| Species                      | _____ |
| Diameter                     | _____ |
| Bearing                      | _____ |
| Distance                     | _____ |

O = Corner

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_

Bearing Trees, Reference Objects

|          |       |
|----------|-------|
| Species  | _____ |
| Diameter | _____ |
| Bearing  | _____ |
| Distance | _____ |

Bearing Trees, Reference Objects

|          |       |
|----------|-------|
| Species  | _____ |
| Diameter | _____ |
| Bearing  | _____ |
| Distance | _____ |

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Remonumentation certificate prepared \_\_\_\_\_

By \_\_\_\_\_

Filed at \_\_\_\_\_

Date \_\_\_\_\_