


Index No. D 25

CASS COUNTY LAND CORNER RECORD

T. 144 R. 29 M. 574 Coordinates: X _____ Y _____
5/16 Corner common to sections 1 And 6-144-28



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - MILO STEFAN - 1977
Doc. # 258604
Set 2" x 60" galvanized steel pipe with
brass cap.
13" W Oak S83W 27.21';
14" Tamarack S12E 75.18';
6" Tamarack N32E 90.38'.

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____