


Index No. E 18

CASS COUNTY LAND CORNER RECORD

T. 144 R. 29 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
w/116 Corner common to sections 2, 11



EXISTING SURVEYS

**Original Government Survey**

Year surveyed 1926  
Original monument 1X36" 11P. w/ brass cap  
Species Poplar Bearing Poplar Trees \_\_\_\_\_  
Diameter 14" 3" \_\_\_\_\_  
Bearing S87E N66W \_\_\_\_\_  
Distance 28 LKS 5 LKS \_\_\_\_\_

**Original Evidence Found**

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

**Original Bearing Trees Found**

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

○ = Corner

**Subsequent Corner Restoration**

Year surveyed 1961 By Pete Meyer  
Location filed \_\_\_\_\_  
Monument Found GLO monument in good condition.

**Evidence of Subsequent Corner Restoration**

Year of search \_\_\_\_\_ By \_\_\_\_\_

**Bearing Trees, Reference Objects**

Species	<u>Oak</u>	<u>Ash</u>	<u>Cedar post</u>
Diameter	<u>8"</u>	<u>4"</u>	<u>4"x4"x6.5'</u>
Bearing	<u>N88E</u>	<u>S30W</u>	<u>South</u>
Distance	<u>33.85'</u>	<u>8.65'</u>	<u>0.6'</u>

**Bearing Trees, Reference Objects**

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

**Subsequent Corner Restoration**

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

**Evidence of Subsequent Corner Restoration Found**

Year of search \_\_\_\_\_ By \_\_\_\_\_  
CERTIFICATE - PETE MEYER - 1961

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_