


Index No. E3

CASS COUNTY LAND CORNER RECORD

T. 144 R. 29 M. 5TH Coordinates: X _____ Y _____
N1/4 7 Corner common to sections 6, 7



EXISTING SURVEYS

Original Government Survey
 Year surveyed 1873
 Original monument Post

Bearing Trees
 Species Cedar Cedar
 Diameter 5" 5"
 Bearing S58W N63W
 Distance 14 LKS 63 LKS

Original Evidence Found
 Year of search _____ By _____
 Monument found _____

Original Bearing Trees Found
 Species _____
 Diameter _____
 Bearing _____
 Distance _____

Subsequent Corner Restoration
 Year surveyed _____ By _____
 Location filed _____
 Monument _____

Bearing Trees, Reference Objects
 Species _____
 Diameter _____
 Bearing _____
 Distance _____

Evidence of Subsequent Corner Restoration
 Year of search _____ By _____

Bearing Trees, Reference Objects

Subsequent Corner Restoration
 Year surveyed _____ By _____
 Location filed _____
 Monument _____

Evidence of Subsequent Corner Restoration Found
 Year of search _____ By _____

1982 Certificate - Anthony Kerick
Doc. # 265251
Found 2" x 5' iron pipe with brass cap.
10" Red Pine N88E 12.45';
8" Red Pine N76E 8.4';
10" J. Pine S25°30'W 15.77'

Remonumentation certificate prepared _____ By _____
 Filed at _____ Date _____