Index No. E 5

# CASS COUNTY LAND CORNER RECORD

T. 144 R. 29 M. 5TH Coordinates: X _____ Y _____

NE 7 Corner common to sections 5, 6, 7, 8



O = Corner

## EXISTING SURVEYS

### Original Government Survey

Year surveyed 1873

Original monument Post

Bearing Trees

| | | | | |
|---|---|---|---|---|
| Species | Cedar | Spruce | Spruce | Cedar |
| Diameter | 10" | 14" | 6" | 12" |
| Bearing | S60W | S50E | N45W | N26E |
| Distance | 7Lks | 23Lks | 60 Lks | 40 Lks |

### Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

| | | | | |
|---|---|---|---|---|
| Species | | | | |
| Diameter | | | | |
| Bearing | | | | |
| Distance | | | | |

### Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Bearing Trees, Reference Objects

| | | | | |
|---|---|---|---|---|
| Species | | | | |
| Diameter | | | | |
| Bearing | | | | |
| Distance | | | | |

### Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

### Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

### Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

CERTIFICATE - PETE MEYER 1958

1982 Certificate - Anthony Kerick
Doc. # 265248
Found 2" x 5' iron pipe with brass cap.
7" Jack Pine N34E 18.2' (dead);
8" Jack Pine N50E 46.20';
7" Jack Pine N80E 53.5' (stump);
11" Jack Pine S58E 29.0' (dead);
11" Jack Pine S12E 48.0'

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____