


Index No. F 21

CASS COUNTY LAND CORNER RECORD

T. 144 R. 29 M. 5TH Coordinates: X _____ Y _____
N 116 Corner common to sections 11, 12



EXISTING SURVEYS

Original Government Survey
Year surveyed 1926
Original monument 1x36" 1 1/2" W Brass cap

Original Evidence Found
Year of search _____ By _____
Monument found _____

Bearing Trees
Species Jilene Jilene
Diameter 12" 8"
Bearing N 7E N 77-30W
Distance 30 LKS 46 LKS

Original Bearing Trees Found
Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration
Year surveyed 1963 By Pete Meyer
Location filed _____
Monument Found GLO monument in good condition.

Evidence of Subsequent Corner Restoration
Year of search _____ By _____

Bearing Trees, Reference Objects
Species Oak W. Pine
Diameter 8" 17"
Bearing N 55W S 58E
Distance 40.4' 62.4'

Bearing Trees, Reference Objects

Subsequent Corner Restoration
Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found
Year of search _____ By _____
CERTIFICATE - PETE MEYER - 1963

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____