


Index No. # 18

CASS COUNTY LAND CORNER RECORD

T. 144 R. 29 M. 5TH Coordinates: X _____ Y _____
SW 1/16 Corner common to sections 11



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1926 SW 1/16 S11
Original monument 1x36" 1 1/2" w/brass 1926
cup

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species Cedar Cedar _____
Diameter 8" 10" _____
Bearing N 40-1/2 E S 45-30 W _____
Distance 12 LKS 17 LKS _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed 1961 By Pete Meyer
Location filed _____
Monument Found GLO monument in good
condition.

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species Cedar Cedar _____
Diameter 10" 7" _____
Bearing S 37 E N 87 1/2 W _____
Distance 22.55' 15.60' _____

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - PETE MEYER - 1961

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____