


Index No. M 13

CASS COUNTY LAND CORNER RECORD

T. 144 R. 29 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
5116 Corner common to sections 15, 16



EXISTING SURVEYS

Original Government Survey

Year surveyed 1926 5116  
Original monument 1836" 1/2 w/ brass cap 516/515  
1926

Species	Bearing	Trees
<u>Ash</u>	<u>Ironwood</u>	
Diameter <u>12"</u>	<u>10"</u>	
Bearing <u>S62E</u>	<u>N6W</u>	
Distance <u>54LKS</u>	<u>13LKS</u>	

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1982 By Gary Stevenson  
Location filed Corner Certificate  
Monument in 1980 USFS find brass cap and  
rotted Ash stub laying on ground S62E  
35.6'

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
<u>w. Pine</u>	<u>26"</u>	<u>N52E</u>	<u>226.08'</u>
<u>Y. Birch</u>	<u>8"</u>	<u>S69E</u>	<u>49.13'</u>
<u>Y. Birch</u>	<u>9"</u>	<u>N34W</u>	<u>61.21'</u>

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Certificate - Gary Stevenson - Filed by USFS  
Doc. # 249376 1984 - dated 1982

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_