


Index No. M 15

CASS COUNTY LAND CORNER RECORD

T. 144 R. 29 M. 57H Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
C.S. 116 Corner common to sections 15



EXISTING SURVEYS

Original Government Survey

Year surveyed 1926  
Original monument 1 x 36" 1/2 pul brass cap S 116 1/2 S 15 C 1926

Bearing Trees	
Species <u>Maple</u>	<u>Ironwood</u>
Diameter <u>8"</u>	<u>8"</u>
Bearing <u>S 89 E</u>	<u>S 88 W</u>
Distance <u>146s</u>	<u>186s</u>

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Original Bearing Trees Found

Species _____	_____	_____	_____
Diameter _____	_____	_____	_____
Bearing _____	_____	_____	_____
Distance _____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1982 By Gary Stevenson  
Location filed Corner Certificate  
Monument in 1980 USFS End brass cap and Maple S 88 W 11.88' - maple was cut down

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Bearing Trees, Reference Objects

Species <u>W. oak</u>	<u>Maple</u>	<u>Y. Birch</u>
Diameter <u>15"</u>	<u>8"</u>	<u>10"</u>
Bearing <u>S 79 E</u>	<u>S 42 W</u>	<u>S 82 W</u>
Distance <u>35.0'</u>	<u>50.9'</u>	<u>101.61'</u>

Bearing Trees, Reference Objects

_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Certificate - Gary Stevenson - Filed by USFS  
Doc. # 279377 1984 - dated 1982

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_