


Index No. N18

CASS COUNTY LAND CORNER RECORD

T. 144 R. 29 M. 5TH Coordinates: X _____ Y _____
W 1/16 Corner common to sections 14, 23



EXISTING SURVEYS

Original Government Survey

Year surveyed 1926
Original monument 1x36" 1/2. w/brass w 1/16 514
cup 523
1926

Species	Bearing	Trees
<u>Spruce</u>	<u>Maple</u>	
<u>10"</u>	<u>6"</u>	
<u>N12W</u>	<u>S46-30W</u>	
<u>24LKS</u>	<u>29LKS</u>	

Original Evidence Found

Year of search _____ By _____
Monument found _____

Original Bearing Trees Found

Species	Diameter	Bearing	Distance

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - Gary Stevenson - 1982
Doc. # 264946
Found GLO monument in good condition
11" Spruce N73W 37.30';
4" Ash N16E 59.12';
11" Y. Birch N88E 77.56';
19" Ash snag S12W 36.40'

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____