


T. 144 R. 29 M. 5TH Coordinates: X _____ Y _____
NE 19 Corner common to sections 17, 18, 19, 20



EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Species	Bearing	Trees	Distance
<u>Poplar</u>	<u>12"</u>	<u>Poplar</u>	<u>31 LKS</u>
<u>Maple</u>	<u>7"</u>	<u>Maple</u>	<u>39 LKS</u>
<u>Birch</u>	<u>6"</u>	<u>Maple</u>	<u>26 LKS</u>
		<u>Birch</u>	<u>17 LKS</u>

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1906 By JOHN CURO
Location filed COUNTY SURVEY RECORD BOOK "A" P240-241
Monument FOUND OLD GOVT B.T.S.: 12" POPLAR N45W 20.5'; 7" POPLAR S19W 25.7'; 6" BIRCH S44E 11.2' SET POST

Evidence of Subsequent Corner Restoration

Year of search 1926 By GLO
Set 2x36" 11" w/bress cap T144N R29W
S18/S17
S19/S20
1926

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
<u>BIRCH</u>	<u>2"</u>	<u>N21E</u>	<u>14.55'</u>
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
<u>Maple</u>	<u>14"</u>	<u>N5E</u>	<u>19 LKS</u>
<u>Maple</u>	<u>6"</u>	<u>S13-30E</u>	<u>35 LKS</u>
<u>Basswood</u>	<u>8"</u>	<u>S54W</u>	<u>37 LKS</u>
<u>Yellow Birch</u>	<u>8"</u>	<u>N26W</u>	<u>40 LKS</u>

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - BILL OKERMAN - 1969
Found GLO monument in good condition
9" W. OAK S71W 37.77';
11" Basswood S70E 44.47';
5" Elm N21E 57.10'