


Index No. P13

CASS COUNTY LAND CORNER RECORD

T. 144 R. 29 M. 574 Coordinates: X _____ Y _____
E 1421 Corner common to sections 21, 22



EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument Post

Bearing Trees	
Species <u>Maple</u>	<u>Ironwood</u>
Diameter <u>6"</u>	<u>3"</u>
Bearing <u>N65E</u>	<u>N35W</u>
Distance <u>37 LKS</u>	<u>42 LKS</u>

Original Evidence Found

Year of search _____ By _____
Monument found _____

Original Bearing Trees Found

Species _____	_____	_____
Diameter _____	_____	_____
Bearing _____	_____	_____
Distance _____	_____	_____

O = Corner

Subsequent Corner Restoration

Year surveyed 1926 By GLO
Location filed Sec. of State
Monument Set 1x3/8" lil. brass cap 1/4
521/522
1926

Evidence of Subsequent Corner Restoration

Year of search 1965 By William Okerman
Found GLO monument in good condition.

Bearing Trees, Reference Objects

Species <u>Maple</u>	<u>Ash</u>
Diameter <u>4"</u>	<u>16"</u>
Bearing <u>N50E</u>	<u>S25W</u>
Distance <u>42 LKS</u>	<u>30 LKS</u>

Bearing Trees, Reference Objects

<u>Y. Birch</u>	<u>Y. Birch</u>
<u>7"</u>	<u>9"</u>
<u>N78W</u>	<u>S69E</u>
<u>35.50'</u>	<u>34.30'</u>

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - BILL OKERMAN - 1965

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____