


Index No. P 17

CASS COUNTY LAND CORNER RECORD

T. 144 R. 29 M. 5TH Coordinates: X _____ Y _____
E 1/4 22 Corner common to sections 22, 23



EXISTING SURVEYS

Original Government Survey
 Year surveyed 1873
 Original monument Post

Bearing Trees	
Species <u>Maple</u>	<u>Basswood</u>
Diameter <u>6"</u>	<u>6"</u>
Bearing <u>N20E</u>	<u>S22W</u>
Distance <u>18 LKS</u>	<u>30 LKS</u>

Original Evidence Found
 Year of search _____ By _____
 Monument found _____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

O = Corner

Subsequent Corner Restoration
 Year surveyed 1926 By GLO
 Location filed Sec. of State
 Monument Set 1x36" Lib. W. Brass cap 114
S22/S23
1926

Evidence of Subsequent Corner Restoration
 Year of search 1963 By PETE MEYER
Found GLO monument in good condition.

Bearing Trees, Reference Objects

Species <u>Ironwood</u>	<u>Ironwood</u>
Diameter <u>4"</u>	<u>6"</u>
Bearing <u>N83-15E</u>	<u>N62W</u>
Distance <u>22 LKS</u>	<u>26 LKS</u>

Bearing Trees, Reference Objects

<u>Maple</u>	<u>Maple</u>	<u>Maple</u>
<u>8"</u>	<u>9"</u>	<u>11"</u>
<u>N11E</u>	<u>S80 1/2 E</u>	<u>S42 1/4 W</u>
<u>17.95'</u>	<u>24.15'</u>	<u>39.9'</u>

Subsequent Corner Restoration
 Year surveyed _____ By _____
 Location filed _____
 Monument _____

Evidence of Subsequent Corner Restoration Found
 Year of search _____ By _____
CERTIFICATE - PETE MEYER - 1963

Remonumentation certificate prepared _____ By _____
 Filed at _____ Date _____