


Index No. R13

CASS COUNTY LAND CORNER RECORD

T. 144 R. 29 M. 5TH Coordinates: X _____ Y _____
NE 28 Corner common to sections 21, 22, 27, 28



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument Post

Bearing Trees			
Species	<u>Balsam</u>	<u>Balsam</u>	<u>Balsam</u>
Diameter	<u>4"</u>	<u>4"</u>	<u>5"</u>
Bearing	<u>N56W</u>	<u>N80E</u>	<u>S14E</u>
Distance	<u>27 LKS</u>	<u>15 LKS</u>	<u>33 LKS</u>

Original Evidence Found

Year of search _____ By _____
Monument found _____

Original Bearing Trees Found

Bearing Trees Found			
Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1926 By GLO
Location filed Sec. of State
Monument Set 2x36" i.p. Wilbruss cap

Bearing Trees, Reference Objects			
Species	<u>Maple</u>	<u>Birch</u>	<u>Balsam</u>
Diameter	<u>10"</u>	<u>10"</u>	<u>8"</u>
Bearing	<u>N10E</u>	<u>S25E</u>	<u>S60-30W</u>
Distance	<u>34 LKS</u>	<u>27 LKS</u>	<u>5 LKS</u>

Evidence of Subsequent Corner Restoration

Year of search 1963 By Pete Meyer
Found GLO monument in good condition

Bearing Trees, Reference Objects

Bearing Trees, Reference Objects			
Species	<u>Birch</u>	<u>Elm</u>	<u>Elm</u>
Diameter	<u>6"</u>	<u>18"</u>	<u>17"</u>
Bearing	<u>N34W</u>	<u>N29E</u>	<u>S67E</u>
Distance	<u>27.1'</u>	<u>75.55'</u>	<u>33.65'</u>

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - PETE MEYER - 1963

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____