


Index No: R 4

CASS COUNTY LAND CORNER RECORD

T. 144 R. 29 M. 5TH Coordinates: X _____ Y _____
E 116 Corner common to sections 19, 30



EXISTING SURVEYS

Original Government Survey

Year surveyed 1926
Original monument 1.1 P. address E 116 S 19
530

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species Elm Maple _____
Diameter 14" 8" _____
Bearing Elm Maple _____
Distance 14" 8" _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed 1963 By Pete Meyer
Location filed _____
Monument Found GLO monument in good condition.

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species Maple Elm _____
Diameter 8" 19" _____
Bearing S 82 W S 77 E _____
Distance 6.8' 44.1' _____

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - PETE MEYER, 1963

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____