


Index No. 511

CASS COUNTY LAND CORNER RECORD

T. 144 R. 29 M. 5TH Coordinates: X _____ Y _____
C.N. 116 Corner common to sections 28



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1926
Original monument 1x36" 11p.w/bress N 1/4 1528
cap 1926

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species Birch Ironwood
Diameter 32" 5"
Bearing N29W S53-45W
Distance 25LKS 29LKS

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed 1963 By PETE MEYER
Location filed _____
Monument Found GLO monument in good condition.

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species Elm Cedar
Diameter 8" 16"
Bearing N16W S12E
Distance 18.7' 54.85'

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - PETE MEYER - 1963

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____