


Index No. V12-13

CASS COUNTY LAND CORNER RECORD

T. 144 R. 29 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
MC # 2 Corner common to sections 28, 33



EXISTING SURVEYS

Original Government Survey

Year surveyed 1873  
Original monument Post

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees

Species	<u>Dead Cedar</u>	<u>Dead Tam</u>	_____	_____
Diameter	<u>12"</u>	<u>14"</u>	_____	_____
Bearing	<u>N73W</u>	<u>S84W</u>	_____	_____
Distance	<u>84 LKS</u>	<u>76 LKS</u>	_____	_____

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1923 By HORACE DUNAWAY  
Location filed COUNTY BOOK D P. 128  
Monument SET WOOD STAKE

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_

Bearing Trees, Reference Objects

Species	<u>TAM</u>	<u>STUB</u>	<u>CEDAR</u>	_____
Diameter	<u>18"</u>	<u>16"</u>	_____	_____
Bearing	<u>S55E</u>	<u>N55W</u>	_____	_____
Distance	<u>17'</u>	<u>56'</u>	_____	_____

Bearing Trees, Reference Objects

_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_