


Index No. W 4

CASS COUNTY LAND CORNER RECORD

T. 144 R. 29 M. 57A Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
NE 1/16 Corner common to sections 31



EXISTING SURVEYS

**Original Government Survey**

Year surveyed 1926  
 Original monument 1x36" I.P.W. brass NE 1/16 S31  
cap 1926

**Bearing Trees**

|          |                |                |       |       |
|----------|----------------|----------------|-------|-------|
| Species  | <u>Elm</u>     | <u>Maple</u>   | _____ | _____ |
| Diameter | <u>8"</u>      | <u>14"</u>     | _____ | _____ |
| Bearing  | <u>S24-30W</u> | <u>N35-15W</u> | _____ | _____ |
| Distance | <u>31 LKS</u>  | <u>76 LKS</u>  | _____ | _____ |

**Original Evidence Found**

Year of search \_\_\_\_\_ By \_\_\_\_\_  
 Monument found \_\_\_\_\_

**Original Bearing Trees Found**

|          |       |       |       |       |
|----------|-------|-------|-------|-------|
| Species  | _____ | _____ | _____ | _____ |
| Diameter | _____ | _____ | _____ | _____ |
| Bearing  | _____ | _____ | _____ | _____ |
| Distance | _____ | _____ | _____ | _____ |

**Subsequent Corner Restoration**

Year surveyed 1962 By PETE MEYER  
 Location filed \_\_\_\_\_  
 Monument found GLO monument in good condition.

**Evidence of Subsequent Corner Restoration**

Year of search \_\_\_\_\_ By \_\_\_\_\_

**Bearing Trees, Reference Objects**

|          |               |                 |       |       |
|----------|---------------|-----------------|-------|-------|
| Species  | <u>Maple</u>  | <u>Maple</u>    | _____ | _____ |
| Diameter | <u>10"</u>    | <u>12"</u>      | _____ | _____ |
| Bearing  | <u>S16-8W</u> | <u>S86-12 E</u> | _____ | _____ |
| Distance | <u>15.6'</u>  | <u>22.75'</u>   | _____ | _____ |

**Bearing Trees, Reference Objects**

|          |       |       |       |       |
|----------|-------|-------|-------|-------|
| Species  | _____ | _____ | _____ | _____ |
| Diameter | _____ | _____ | _____ | _____ |
| Bearing  | _____ | _____ | _____ | _____ |
| Distance | _____ | _____ | _____ | _____ |

**Subsequent Corner Restoration**

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
 Location filed \_\_\_\_\_  
 Monument \_\_\_\_\_

**Evidence of Subsequent Corner Restoration Found**

Year of search \_\_\_\_\_ By \_\_\_\_\_  
CERTIFICATE - PETE METER - 1962

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
 Filed at \_\_\_\_\_ Date \_\_\_\_\_