


T. 144 R. 30 M. 5th Coordinates: X _____ Y _____
N 1/4 3 Corner common to sections 3 and 34/145/30



EXISTING SURVEYS

Original Government Survey

Year surveyed 5/1930, H.D. Craig, US Surveyor 1/4 S3

Original monument Set 1"x 36" iron pipe w/brass cap 1930

S 89°45' W, 1.09 Chains(71.94') from SW Sec. 35

Original Evidence Found

Year of search 1964 by Okerman

Monument found GLO iron

USFS Book 1, page 5

Bearing Trees

Species	<u>Elm</u>	<u>White Pine</u>
Diameter	<u>12"</u>	<u>21"</u>
Bearing	<u>S 23° E</u>	<u>S 40° W</u>
Distance	<u>145 links</u>	<u>69 links</u>

Original Bearing Trees Found

Species	<u>Elm</u>	<u>White Pine</u>
Diameter	<u>13"</u>	<u>29"</u>
Bearing	<u>S 22° E</u>	<u>S 41°30' W</u>
Distance	<u>95.6'</u>	<u>45.5'</u>

Subsequent Corner Restoration

Year surveyed 4/1964 By W.H. Okerman, LS 6807

Location filed: USFS Book 1, page 5

Monument: Found 1" GLO iron pipe with brass cap and original witnesses in excellent shape, placed 54-4 sign on 6" Birch, N 36° W, 9.2'

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Location filed: _____

Monument: _____

Bearing Trees, Reference Objects

Species	<u>Elm</u>	<u>White Pine</u>
Diameter	<u>13"(1930)</u>	<u>29"(1930)</u>
Bearing	<u>S 22° E</u>	<u>S 41°30' W</u>
Distance	<u>95.6'</u>	<u>45.5'</u>

Bearing Trees, Reference Objects

Species	_____	_____
Diameter	_____	_____
Bearing	_____	_____
Distance	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed: _____

Monument: _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Location filed: _____

Monument: _____

