


T. 144 R. 30 M. 5th Coordinates: X _____ Y _____

N 1/4 1 Corner common to sections 1 and 36/145/30



● = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 5/1930, H.D. Craig, US Surveyor 1/4 S1
 Original monument Set 1"x 36" iron pipe w/brass cap 1930
S 89°20' W, 9.43 Chains(622.38') from SE Sec. 36

Original Evidence Found

Year of search 1936 by CCC
 Monument found GLO iron
 Form 874-9

Bearing Trees

Species	<u>Ash</u>	<u>Birch</u>	_____
Diameter	<u>6"</u>	<u>15"</u>	_____
Bearing	<u>S 66° E</u>	<u>S 81 1/2° W</u>	_____
Distance	<u>41 links</u>	<u>83 links</u>	_____

Original Bearing Trees Found

Species	<u>Ash</u>	<u>Birch</u>	_____
Diameter	<u>5"</u>	<u>12"</u>	_____
Bearing	<u>S 67°30' E</u>	<u>S 30° W</u>	_____
Distance	<u>40.9 links</u>	<u>81.14 links</u>	_____

Subsequent Corner Restoration

Year surveyed 12/1936 By L. Folsom, CCC
 Location filed: Form 874-9
 Monument: Found metal pipe with cap up 6" in good condition and GLO witnesses.

Evidence of Subsequent Corner Restoration

Year of search 11/1965 By J. Ekstrom, USFS
 Location filed: USFS Book 1, page 7
 Monument: Found 1" GLO iron pipe with brass cap and original Ash witness fallen, rotted and marked new witnesses as follows.

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Bearing Trees, Reference Objects

Species	<u>Ash</u>	<u>Elm</u>	_____
Diameter	<u>10"</u>	<u>8"</u>	_____
Bearing	<u>S 29° E</u>	<u>S 65° W</u>	_____
Distance	<u>14.5'</u>	<u>19.6'</u>	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
 Location filed: _____
 Monument: _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
 Location filed: _____
 Monument: _____

