


Index No. A.0-05.0

CASS COUNTY LAND CORNER RECORD

T. 144 R. 30 M. 5th Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_

NE 6 Corner common to sections 5, 6 and 32/145/30



EXISTING SURVEYS

Original Government Survey

Year surveyed 1875

Original monument Post

1.15 Chains(75.90') west of S 1/4 Sec. 32/145/30

Bearing Trees

Species	<u>Norway Pine</u>	<u>White Pine</u>	_____
Diameter	<u>24"</u>	<u>30"</u>	_____
Bearing	<u>S 22° W</u>	<u>S 71° E</u>	_____
Distance	<u>50 links</u>	<u>40 links</u>	_____

Original Evidence Found

Year of search 1930 by Craig

Monument found \_\_\_\_\_

Historical Society Notes

Original Bearing Trees Found

Species	<u>W. Pine Stump</u>	<u>N. Pine stump</u>	_____
Diameter	<u>30"</u>	<u>26"</u>	_____
Bearing	<u>S 71° E</u>	<u>S 22° W</u>	_____
Distance	<u>40 links</u>	<u>50 links</u>	_____

Subsequent Corner Restoration

Year surveyed 5/1930 By H.D. Craig, US Surveyor

Location filed: Minnesota Historical Soc., Notes T145N R30W

Monument: Set 2"x 36" iron pipe with brass cap  
 from original witnesses and marked new  
 witnesses as follows.

S32  
S6 | S5  
T144N R30W  
CC  
1930

Bearing Trees, Reference Objects

Species	<u>White Oak</u>	<u>Poplar</u>	_____
Diameter	<u>6"</u>	<u>5"</u>	_____
Bearing	<u>S 21° E</u>	<u>S 62 1/2° W</u>	_____
Distance	<u>132 links</u>	<u>23 links</u>	_____

Evidence of Subsequent Corner Restoration

Year of search 8/1934 By J.A. Gjelhaug, Eng. CCC

Location filed: Form 874-9

Monument: Brass capped pipe in good condition, up 10" and witnesses.

Bearing Trees, Reference Objects

Species	<u>W. Oak</u>	<u>Aspen</u>	_____
Diameter	<u>7"</u>	<u>6"</u>	_____
Bearing	<u>S 20°45' E</u>	<u>S 64° W</u>	_____
Distance	<u>131 links</u>	<u>23 links</u>	_____

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_

Location filed: \_\_\_\_\_

Monument: \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_


Location filed: \_\_\_\_\_

Monument: \_\_\_\_\_

Index No. A5

CASS COUNTY LAND CORNER RECORD

T. 144 R. 30 M. 5th Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
NE 6 Corner common to sections 5, 6



EXISTING SURVEYS

Original Government Survey

Year surveyed 1875  
Original monument Post  
1.15 ch. W. of S 1/4 Sec 32

Bearing Trees

Species N. Pine W. Pine  
Diameter 24" 30"  
Bearing S22W S71E  
Distance 50LKS 40LKS

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Original Bearing Trees Found

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed 1930 By GLO  
Location filed Sec of State  
Monument End both orig B.T. stumps Set 2x36"  
h.P. w/ brass cap 7145 N R30W  
532

Bearing Trees, Reference Objects

Species W OAK Poplar  
Diameter 6" 5"  
Bearing S21E S62 1/2 W  
Distance 132 LKS 23 LKS

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_

Bearing Trees, Reference Objects

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_