


Index No. C.0-23.0

CASS COUNTY LAND CORNER RECORD

T. 144 R. 30 M. 5th Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_

C 1/4 Corner common to sections 1



EXISTING SURVEYS

Original Government Survey

Original Evidence Found

Year surveyed 6/1930, H.D. Craig, US Surveyor C 1/4 S1  
Original monument Set 1"x36" iron with brass cap 1930

Year of search \_\_\_\_\_ by \_\_\_\_\_  
Monument found \_\_\_\_\_

Resurvey Notes, MN Historical Society

Bearing Trees

Species	<u>Norway Pine</u>	<u>Norway Pine</u>	_____
Diameter	<u>12"</u>	<u>16"</u>	_____
Bearing	<u>S 18 3/4° E</u>	<u>S 18 3/4° W</u>	_____
Distance	<u>82 links</u>	<u>170 links</u>	_____

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 12/1936 By L. Folsom, CCC  
Location filed: USFS Form 874-9  
Monument: Metal Pipe  
Capped in good condition, up 3" and witnesses.

Evidence of Subsequent Corner Restoration

Year of search 9/1986 By C.R. Krause, USFS  
Location filed: USFS Book 2, page 78  
Monument: Found GLO iron pipe with brass cap up 8", 170' W. of new Rd #21352, small wet sough 50' SW and witnessed as follows. Pine stp., S 19° W, 112.2'(1930) rotted Steel Sign Post, North, 3.4' warning sign Steel Sign Post, South, 3.7' warning sign

Bearing Trees, Reference Objects

Species	<u>Norway</u>	<u>Norway</u>	_____	_____
Diameter	<u>10"(1930)</u>	<u>15"(1930)</u>	_____	_____
Bearing	<u>S 19° E</u>	<u>S 18°30' W</u>	_____	_____
Distance	<u>81.81 links</u>	<u>1.7 chains</u>	_____	_____

Bearing Trees, Reference Objects

Species	<u>Norway Pine</u>	<u>Norway Pine</u>	<u>White Oak</u>	<u>White Oak</u>
Diameter	<u>24"(1930)</u>	<u>12"</u>	<u>10"</u>	<u>5"</u>
Bearing	<u>S 19° E</u>	<u>N 84° E</u>	<u>N 11° E</u>	<u>S 52° E</u>
Distance	<u>54.12'</u>	<u>99.75'</u>	<u>47.50'</u>	<u>55.00'</u>

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed: \_\_\_\_\_  
Monument: \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Location filed: \_\_\_\_\_  
Monument: \_\_\_\_\_

