


T. 144 R. 30 M. 5th Coordinates: X _____ Y _____
E 1/4 6 Corner common to sections 5, 6



EXISTING SURVEYS

Original Government Survey		Original Evidence Found	
Year surveyed <u>1875</u>		Year of search _____ by _____	
Original monument <u>Post</u>		Monument found _____	

Bearing Trees			
Species	<u>Red Oak</u>	<u>Sugar</u>	_____
Diameter	<u>16"</u>	<u>14"</u>	_____
Bearing	<u>S 68° W</u>	<u>N 60° E</u>	_____
Distance	<u>170 links</u>	<u>118 links</u>	_____

Original Bearing Trees Found			
Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration	
Year surveyed <u>5/1930</u> By <u>H.D. Craig, US Surveyor</u>	
Location filed: <u>Minn. Historical Society, notes</u>	<u>1/4</u>
Monument: <u>Set 1"x36" iron pipe with brass cap at prorated position and witnesses as follows.</u>	<u>S6 S5</u> <u>1930</u>

Evidence of Subsequent Corner Restoration	
Year of search <u>8/1934</u> By <u>J.A. Gjelhaug, Eng. CCC</u>	
Location filed: <u>Form 874-9</u>	
Monument: <u>Found Brass capped pipe up 8" in good condition and witnesses as follow.</u>	

Bearing Trees, Reference Objects			
Species	<u>Ironwood</u>	<u>Poplar</u>	_____
Diameter	<u>5"</u>	<u>6"</u>	_____
Bearing	<u>S 40 1/2° E</u>	<u>S 44 1/2° W</u>	_____
Distance	<u>10 links</u>	<u>20 links</u>	_____

Bearing Trees, Reference Objects			
Species	<u>Ironwood</u>	<u>Aspen</u>	<u>Ironwood</u>
Diameter	<u>5"(1930)</u>	<u>6"(1930)</u>	<u>6"</u>
Bearing	<u>S 40° E</u>	<u>S 45° W</u>	<u>N 20° E</u>
Distance	<u>9 1/4 links</u>	<u>21 links</u>	<u>0.06 1/2 chains</u>

Subsequent Corner Restoration	
Year surveyed <u>9/1981</u> By <u>C.R. Krause, USFS</u>	
Location filed: <u>USFS Book 1, page 59</u>	
Monument: <u>Found GLO brass capped pipe up 12" in good condition, corner in Experimental Forest, plan to clear cut, witnesses as follow.</u>	
<u>14" Aspen, S 44° W, 13.9'(1930) scribe closed</u>	
<u>Steel Sign Post, North, 5.0' 54-9 sign</u>	
<u>Steel Sign Post, South, 5.0' 54-9 sign</u>	
<u>Steel Sign Post, West, 5.0' 54-9 sign</u>	
<u>4" Post, beside iron, 54-9 sign</u>	
<u>9/1982, G.H. Stevenson, LS 12684</u>	
<u>Certificate of Location</u>	
<u>Found GLO brass capped iron pipe and witnesses from USFS.</u>	

Evidence of Subsequent Corner Restoration Found	
Year of search _____ By _____	
Location filed: _____	
Monument: _____	

