


T. 144 R. 30 M. 5th Coordinates: X _____ Y _____

E 1/4 5 Corner common to sections 4, 5



EXISTING SURVEYS

Original Government Survey

Year surveyed 1875

Original monument Post

Original Evidence Found

Year of search 1930 by Craig

Monument found _____

Minn. Historical Society, notes _____

Bearing Trees

Species	<u>Sugar</u>	<u>White Pine</u>
Diameter	<u>9"</u>	<u>30"</u>
Bearing	<u>S 87° W</u>	<u>N 20° E</u>
Distance	<u>240 links</u>	<u>10 links</u>

Original Bearing Trees Found

Species	<u>White Pine</u>
Diameter	<u>stump</u>
Bearing	<u>N 20° E</u>
Distance	<u>10 links</u>

Subsequent Corner Restoration

Year surveyed 5/1930 By H.D. Craig, US Surveyor

Location filed: Minn. Historical Society, notes 1/4

Monument: Set 1"x36" iron pipe with brass cap S5 | S4
from original witness, at NW side of Spruce and 1930
Cedar swamp and witnesses as follows.

Evidence of Subsequent Corner Restoration

Year of search 10/1934 By J.A. Gjelhaug, Eng. CCC

Location filed: Form 874-9

Monument: Found Brass capped pipe
up 8" in good condition, W. of Cuba Hill Rd. and witnesses as
follow.

Bearing Trees, Reference Objects

Species	<u>Spruce</u>	<u>Maple</u>
Diameter	<u>14"</u>	<u>6"</u>
Bearing	<u>N 2 1/2° E</u>	<u>S 73° W</u>
Distance	<u>32 links</u>	<u>74 links</u>

Bearing Trees, Reference Objects

Species	<u>White Spruce</u>	<u>Hard Maple</u>	<u>Balsam</u>
Diameter	<u>13"(1930)</u>	<u>7"(1930)</u>	<u>5"</u>
Bearing	<u>N 10° E</u>	<u>S 73°30' W</u>	<u>S 6° W</u>
Distance	<u>31 links</u>	<u>73 1/2 links</u>	<u>0.05 chains</u>

Subsequent Corner Restoration

Year surveyed 2/1975 By C.R. Krause, USFS

Location filed: USFS Book 1, page 19

Monument: Found GLO brass capped pipe
up 8" in good condition, 300'+/-, W. of Cuba Hill Rd., 20' W. of
small Spruce swamp and witnesses as follow.
Pine stub, N 20° E, 6.6'(1875) 5' high, scribe still visible
10" Maple, S 73° W, 48.8'(1930) scribe overgrown
10" Black Spruce, S 55° E, 39.6' scribed
6" Ash, S 23° W, 58.3' scribed
7" Maple, N 70° W, 52.0' scribed
Steel Sign Post, South, 2.7' 54-2 and 54-4 signs
4" Cedar Post, West, 10.7'

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Location filed: _____

Monument: _____

