


Index No. D.0-21.0

CASS COUNTY LAND CORNER RECORD

T. 144 R. 30 M. 5th Coordinates: X _____ Y _____

WC S 1/16 Corner common to sections 1, 2

N 2°33' E 0.26 chains(17.16')



EXISTING SURVEYS

Original Government Survey

Year surveyed 5/1930, H.D. Craig, US Surveyor WC
 Original monument Set 1"x 36" iron pipe w/brass cap S1/16
 Corner falls in creek, set witness to corner S2/S1
 1930

Original Evidence Found

Year of search 1994 by USFS
 Monument found GLO iron
 USFS Book 2, page 70

Bearing Trees

Species Cedar stake
 Diameter 5"x 5"
 Bearing 3' in ground
 Distance along side

Original Bearing Trees Found

Species _____
 Diameter _____
 Bearing _____
 Distance _____

Subsequent Corner Restoration

Year surveyed 3/1994 By C.R. Krause, USFS
 Location filed: USFS Book 2, page 70
 Monument: Found iron with cap in marsh grass, placed 8' steel post along side with 4" above ice, 75' E. to creek bank, 58' S. to creek band and witnessed.

Evidence of Subsequent Corner Restoration

Year of search _____ By _____
 Location filed: _____
 Monument: _____

Bearing Trees, Reference Objects

Species Steel Sign
 Diameter Post
 Bearing South
 Distance 20.0'

Bearing Trees, Reference Objects

Species _____
 Diameter _____
 Bearing _____
 Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
 Location filed: _____
 Monument: _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
 Location filed: _____
 Monument: _____

