


Index No. D.0-22.0

CASS COUNTY LAND CORNER RECORD

T. 144 R. 30 M. 5th Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_

SW 1/16 Corner common to sections 1



EXISTING SURVEYS

Original Government Survey

Year surveyed 5/1930, H.D. Craig, US Surveyor SW 1/16  
 Original monument Set 1"x 36" iron pipe w/brass cap S1  
 1930

Original Evidence Found

Year of search 1936 by CCC  
 Monument found GLO iron  
 Form 874-9

Bearing Trees

|          |                    |                   |       |
|----------|--------------------|-------------------|-------|
| Species  | <u>Birch</u>       | <u>Cedar</u>      | _____ |
| Diameter | <u>8"</u>          | <u>10"</u>        | _____ |
| Bearing  | <u>S 33 3/4° E</u> | <u>N 8 1/2° W</u> | _____ |
| Distance | <u>46 links</u>    | <u>35 links</u>   | _____ |

Original Bearing Trees Found

|          |                   |                   |       |
|----------|-------------------|-------------------|-------|
| Species  | <u>Cedar</u>      | <u>Birch</u>      | _____ |
| Diameter | <u>10"</u>        | <u>8"</u>         | _____ |
| Bearing  | <u>N 9° E</u>     | <u>S 35° E</u>    | _____ |
| Distance | <u>35.5 links</u> | <u>45.5 links</u> | _____ |

Subsequent Corner Restoration

Year surveyed 12/1936 By L. Folsom, CCC  
 Location filed: Form 874-9  
 Monument: Found metal pipe with cap up 4" in good condition and GLO witnesses.

Evidence of Subsequent Corner Restoration

Year of search 1969 By L Martinson, USFS  
 Location filed: USFS Book 2, page 72 and Form R9-7150-4  
 Monument: Found brass cap and GLO Cedar stump.

Bearing Trees, Reference Objects

|          |       |       |       |
|----------|-------|-------|-------|
| Species  | _____ | _____ | _____ |
| Diameter | _____ | _____ | _____ |
| Bearing  | _____ | _____ | _____ |
| Distance | _____ | _____ | _____ |

Bearing Trees, Reference Objects

|          |       |       |       |
|----------|-------|-------|-------|
| Species  | _____ | _____ | _____ |
| Diameter | _____ | _____ | _____ |
| Bearing  | _____ | _____ | _____ |
| Distance | _____ | _____ | _____ |

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
 Location filed: \_\_\_\_\_  
 Monument: \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
 Location filed: \_\_\_\_\_  
 Monument: \_\_\_\_\_

