


T. 144 R. 30 M. 5th Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_

E 1/16 Corner common to sections 2, 11



● = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 6/1930, H.D. Craig, US Surveyor 1/4 S2  
Original monument Set 1"x36" iron pipe with brass cap S11  
1930

Original Evidence Found

Year of search \_\_\_\_\_ by \_\_\_\_\_  
 Monument found \_\_\_\_\_

Resurvey Notes, MN Historical Society

Bearing Trees

|          |                    |                   |       |
|----------|--------------------|-------------------|-------|
| Species  | <u>Norway Pine</u> | <u>White Pine</u> | _____ |
| Diameter | <u>10"</u>         | <u>10"</u>        | _____ |
| Bearing  | <u>S 70° W</u>     | <u>N 2 1/4° W</u> | _____ |
| Distance | <u>11 links</u>    | <u>98 links</u>   | _____ |

Original Bearing Trees Found

|          |       |       |       |
|----------|-------|-------|-------|
| Species  | _____ | _____ | _____ |
| Diameter | _____ | _____ | _____ |
| Bearing  | _____ | _____ | _____ |
| Distance | _____ | _____ | _____ |

Subsequent Corner Restoration

Year surveyed 11/1934 By D.J. Sutton, Compassman CCC  
 Location filed: Form 874-9  
 Monument: Found 1" iron pipe with brass cap up 9", in good condition and witnesses as follow.

Bearing Trees, Reference Objects

|          |                     |                   |       |
|----------|---------------------|-------------------|-------|
| Species  | <u>Norway Pine</u>  | <u>White Pine</u> | _____ |
| Diameter | <u>9"</u>           | <u>8"</u>         | _____ |
| Bearing  | <u>S 72°45' W</u>   | <u>N 4°30' W</u>  | _____ |
| Distance | <u>11 1/2 links</u> | <u>98 links</u>   | _____ |

Evidence of Subsequent Corner Restoration

Year of search 3/1994 By C.R. Krause, USFS  
 Location filed: USFS Book 3, page 2  
 Monument: Found iron with brass cap bent over, on island, 200' E. of Tamarack swamp and witnesses as follows.

Bearing Trees, Reference Objects

|          |                    |                        |       |
|----------|--------------------|------------------------|-------|
| Species  | <u>Norway Pine</u> | <u>White Pine stp.</u> | _____ |
| Diameter | <u>24"(1930)</u>   | <u>17"(1930)</u>       | _____ |
| Bearing  | <u>S 70° W</u>     | <u>N 2° W</u>          | _____ |
| Distance | <u>7.26'</u>       | <u>64.7'</u>           | _____ |

Subsequent Corner Restoration

Year surveyed 3/1994 By R. Main, USFS  
 Location filed: USFS Book 3, page 2  
 Monument: Straighten brass capped iron pipe up 8" near SW corner of island, Pine witnesses are the last Pine at SW part of island, witnesses as follows.  
24" Norway Pine, S 70° W, 7.50'(1930) new spike, rescribed  
28" Norway Pine, N 71° E, 21.57' scribed E 1/16 S 2 BT  
25.5" Norway Pine, N 5° W, 90.92' scribed E 1/16 S 2 BT  
Steel Sign Post, North, 4.65'  
Steel Sign Post, South, 3.90'

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
 Location filed: \_\_\_\_\_  
 Monument: \_\_\_\_\_

