


T. 144 R. 30 M. 5th Coordinates: X _____ Y _____

NE 11 Corner common to sections 1, 2, 11, 12



● = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1875
Original monument Post

Original Evidence Found

Year of search 1930 by Craig
Monument found _____
Minn. Hist. Society, notes 47

Bearing Trees


Species	<u>Jack Pine</u>	<u>Jack Pine</u>	<u>Jack Pine</u>	<u>Jack Pine</u>
Diameter	<u>9"</u>	<u>14"</u>	<u>10"</u>	<u>6"</u>
Bearing	<u>S 78° W</u>	<u>S 47° E</u>	<u>N 37° E</u>	<u>N 87° W</u>
Distance	<u>148 links</u>	<u>71 links</u>	<u>56 links</u>	

Original Bearing Trees Found

Species	<u>Norway Pine</u>			
Diameter	<u>22"</u>			
Bearing	<u>N 37° E</u>			
Distance	<u>56 links</u>			

Subsequent Corner Restoration

Year surveyed 5/1930 By H.D. Craig, US Surveyor
Location filed: Minn. Hist. Society, notes pg. 47 T144N R30W
Monument: Set 6"x26" Conc. cyl. with brass cap
up 4", from remains of original witness tree
and marked new witnesses as follows.



Evidence of Subsequent Corner Restoration

Year of search 11/1934 By D.J. Sutton, Compassman CCC
Location filed: Form 874-9
Monument: Found brass cap in concrete
up 5" in good condition, placed a metal location poster on the
NE BT and notes witnesses as follow.

Bearing Trees, Reference Objects

Species	<u>Oak</u>	<u>Maple</u>	<u>Jack Pine</u>	
Diameter	<u>5"</u>	<u>9"</u>	<u>14"</u>	
Bearing	<u>S 64 1/2° E</u>	<u>S 66 3/4° W</u>	<u>N 68 1/2° W</u>	
Distance	<u>174 links</u>	<u>137 links</u>	<u>97 links</u>	

Bearing Trees, Reference Objects

Species	<u>White Oak</u>	<u>Norway Pine</u>	<u>Jack Pine</u>	<u>Soft Maple</u>
Diameter	<u>4"(1930)</u>	<u>4"(1875)</u>	<u>14"(1930)</u>	<u>7"(1930)</u>
Bearing	<u>S 66°30' E</u>	<u>N 36°30' E</u>	<u>N 70°30' W</u>	<u>S 65° W</u>
Distance	<u>174 links</u>	<u>56 links</u>	<u>97 links</u>	<u>137 links</u>

Subsequent Corner Restoration

Year surveyed 11/1936 By L. Folsom, CCC
Location filed: Form 874-9
Monument: Found metal pipe capped
up 3" in good condition and witnesses as follow.
18" Norway, N 36°30' E, 56 links(36.96')(1930)
12" Jack Pine, N 71° W, 96 links(63.36')(1930)

3/1994, C.R. Krause, USFS
USFS Book 2, page 68
Found GLO concrete with brass cap, up 4", at SE end of
Island and witnesses as follow.
26" Norway Pine, N 37° E, 36.71'(1875) rescribed BT
9"& 14" Twin White Oaks, S 64° E, 114.84'(1930) chewed
18" Jack Pine stub, N 68° W, 64.02'(1930) 35' stub
12" White Oak, S 3° E, 46.55' spike, scribed S 12 BT
Steel Sign Post, North, 3.80'
Steel Sign Post, South, 4.35'

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed:
Monument:

