


T. 144 R. 30 M. 5th Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
NE 16 Corner common to sections 9, 10, 15, 16



EXISTING SURVEYS

Original Government Survey

Year surveyed 1875  
Original monument Post

Original Evidence Found

Year of search \_\_\_\_\_ by \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees

Species	Sugar	Sugar	White Birch	Burr Oak
Diameter	4"	4"		4"
Bearing	S 58° E	N 56° W	N 48° E	S 35° W
Distance	14 links	20 links	29 links	27 links

Original Bearing Trees Found

Species				
Diameter				
Bearing				
Distance				

Subsequent Corner Restoration

Year surveyed 6/1930 By H.D. Craig, US Surveyor  
Location filed: Minn. Hist. Society, notes T144N R30W  
Monument: Set 2"x36" iron pipe with brass cap at proportionate position and marked new witnesses trees as follows. S9 | S10  
S16 | S15  
1930

Evidence of Subsequent Corner Restoration

Year of search 9/1934 By C.R. DuBois, Compassman CCC  
Location filed: Form 874-9  
Monument: Found brass capped pipe up 4" in good condition, placed a metal location poster on the NW witness and notes witnesses as follow.

Bearing Trees, Reference Objects

Species	Poplar	White Pine	Elm	Burr Oak
Diameter	8"	16"	14"	8"
Bearing	N 59° E	S 45 1/4° E	S 47 1/2° W	N 54 1/4° W
Distance	32 links	207 links	133 links	10 links

Bearing Trees, Reference Objects

Species	Aspen	Aspen	Elm	White Pine
Diameter	8"(1930)	6"	13"(1930)	15"(1930)
Bearing	N 61° E	N 55° W	S 52°45' W	S 45°30' E
Distance	31 1/4 links	10 links	132 1/4 links	206 1/4 links

Subsequent Corner Restoration

Year surveyed 3/1975 By C.R. Krause, USFS  
Location filed: USFS Book 1, page 36  
Monument: Found GLO brass capped iron pipe up 6" in good condition, 1050' N. of Pay-She-Cummings Rd. and witnesses as follow.  
18" Poplar, N 59° E, 21.1'(1930) scribe rotted  
22" White Pine stump, S 46° E, 136.6'(1930) scribe visible  
16" Elm, S 48° W, 87.8'(1930) scribe rotted out  
10" Poplar, N 54° W, 6.6'(1930)FSLP overgrown, scribe visible  
8" Elm, N 30° E, 42.5' scribed  
20" White Oak, S 66° E, 86.8' scribed  
7" White Spruce, N 87° E, 18.3' scribed  
11" Elm, N 3° W, 62.8' scribed  
7" Ash, N 55° W, 45.9' scribed  
6" Ash, S 25° W, 39.9' scribed  
13" White Oak, South, 1050' FSLP  
Steel Sign Post, North, 1.6' 54-4 sign


Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Location filed:  
Monument:

Index No. J13

CASS COUNTY LAND CORNER RECORD

T. 144 R. 30 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
NE 16 Corner common to sections 9, 10, 15, 16



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1875  
Original monument Post

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

		Bearing Trees	
Species	<u>Sugar</u>	<u>Sugar</u>	<u>W. Birch</u>
Diameter	<u>4"</u>	<u>4"</u>	<u>4"</u>
Bearing	<u>S58E</u>	<u>N56W</u>	<u>N48E</u>
Distance	<u>14LKS</u>	<u>20LKS</u>	<u>27LKS</u>

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1930 By GLO  
Location filed Sec. of State  
Monument Set 2x36" 1/2" w/dress cap T144N R30W  
59/510  
516/515  
1930

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

		Bearing Trees		Reference Objects	
Species	<u>Poplar</u>	<u>W. Pine</u>	<u>Elm</u>	<u>Br. oak</u>	
Diameter	<u>8"</u>	<u>16"</u>	<u>14"</u>	<u>8"</u>	
Bearing	<u>N59E</u>	<u>S45 1/2 E</u>	<u>S47 1/2 W</u>	<u>N54 1/4 W</u>	
Distance	<u>32LKS</u>	<u>207LKS</u>	<u>133LKS</u>	<u>10LKS</u>	

Bearing Trees, Reference Objects

_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
CERTIFICATE - MILO STEFAN - 1975 - FILED IN 1980  
Doc. # 252595  
Found GLO monument in good condition  
8" Elm N30E 42.50';  
20" W. OAK S60E 80.80';  
7" White Spruce N87E 18.30';  
11" Elm N3W 62.80';  
7" Ash N55W 45.90';  
6" Ash S25W 39.90'

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_