


T. 144 R. 30 M. 5th Coordinates: X _____ Y _____
N 1/4 15 Corner common to sections 10, 15



EXISTING SURVEYS

Original Government Survey

Year surveyed 1875
Original monument Post

Original Evidence Found

Year of search 1930 by Craig
Monument found _____
Minn. Hist. Society, notes pg 106

Bearing Trees

Species	<u>Balsam</u>	<u>White Pine</u>
Diameter	<u>4"</u>	<u>6"</u>
Bearing	<u>N 30° W</u>	<u>S 34° E</u>
Distance	<u>7 links</u>	<u>13 links</u>

Original Bearing Trees Found

Species	<u>White Pine</u>	<u>Balsam</u>
Diameter	<u>12" stub</u>	<u>rotted stump</u>
Bearing	<u>S 34° E</u>	<u>N 30° W</u>
Distance	<u>13 links</u>	<u>7 links</u>

Subsequent Corner Restoration

Year surveyed 7/1930 By H.D. Craig, US Surveyor
Location filed: Minn. Hist. Society, notes pg. 106 1/4 S10
Monument: Set 1"x36" iron pipe with brass cap S15
up 6", from remains of original witnesses and 1930
marked new witnesses as follows.

Evidence of Subsequent Corner Restoration

Year of search 10/1934 By D.J. Sutton, Compassman CCC
Location filed: Form 874-9
Monument: Found 1" brass capped pipe
up 6" in good condition, W. of old R.R. grade and notes
witnesses as follow.

Bearing Trees, Reference Objects

Species	<u>White Pine</u>	<u>White Pine</u>
Diameter	<u>18"</u>	<u>14"</u>
Bearing	<u>S 51 1/4° E</u>	<u>N 23 1/4° W</u>
Distance	<u>145 links</u>	<u>197 links</u>

Bearing Trees, Reference Objects

Species	<u>White Pine</u>	<u>White Pine</u>
Diameter	<u>20"(1930)</u>	<u>18"(1930)</u>
Bearing	<u>S 52° E</u>	<u>N 24° W</u>
Distance	<u>143 links</u>	<u>196 links</u>

Subsequent Corner Restoration

Year surveyed 2/1975 By C.R. Krause, USFS
Location filed: USFS Book 1, page 37
Monument: Found GLO iron pipe with brass cap
up 8" in good condition, at NE corner of Aspen regen, 150' S.
of Pay-She-Cummings Rd., 35' W. of FW #133 and witnesses.
27" White Pine, S 51° E, 95.7'(1930) scribe visible
22" White Pine, N 23° W, 130.0'(1930) scribe rotted out
6" White Oak, North, 10.9' scribed
10" White Spruce, N 85° W, 31.4' scribed
Steel Sign Post, East, 2.8' 54-4 sign


Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed:
Monument:

Index No. J15

CASS COUNTY LAND CORNER RECORD

T. 144 R. 30 M. 5TH Coordinates: X _____ Y _____
N 1/4 15 Corner common to sections 10, 15



EXISTING SURVEYS

Original Government Survey

Year surveyed 1875
Original monument Post

Species	Bearing	Trees
<u>Balsam</u>	<u>W</u>	<u>W Pine</u>
Diameter <u>4"</u>		<u>6"</u>
Bearing <u>N30W</u>		<u>S34E</u>
Distance <u>7LKS</u>		<u>13LKS</u>

Original Evidence Found

Year of search _____ By _____
Monument found _____

Original Bearing Trees Found

Species	Bearing	Distance
_____	_____	_____
_____	_____	_____
_____	_____	_____
_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1930 By GLO
Location filed Sec. of State
Monument End Stumps of both B.T.S set 1x36" 1/2.
w/brass cap 1/4 510
515
1930

Bearing Trees, Reference Objects

Species	Bearing	Distance
<u>W Pine</u>	<u>W Pine</u>	
Diameter <u>18"</u>	<u>14"</u>	
Bearing <u>S57 1/4 E</u>	<u>N23 1/4 W</u>	
Distance <u>145 LKS</u>	<u>197 LKS</u>	

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species	Bearing	Distance
_____	_____	_____
_____	_____	_____
_____	_____	_____
_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - MILO STEFAN - 1975 FILED IN 1980
Doc. # 258594
Found GLO monument in good condition
6" W. Oak North 1080';
10" White Spruce N85 W 31.40'

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____