


T. 144 R. 30 M. 5th Coordinates: X _____ Y _____
NE 15 Corner common to sections 10, 11, 14, 15



EXISTING SURVEYS

Original Government Survey

Year surveyed 1875
Original monument Post

Original Evidence Found

Year of search 1900 by COE
Monument found _____
Leech Lake Reservoir Map

Bearing Trees

Species	<u>White Pine</u>	<u>Aspen</u>	<u>Maple</u>	<u>Balsam</u>
Diameter	<u>8"</u>	<u>8"</u>	<u>5"</u>	<u>9"</u>
Bearing	<u>N 42° E</u>	<u>N 60° W</u>	<u>S 30° E</u>	<u>S 58° W</u>
Distance	<u>27 links</u>	<u>40 links</u>	<u>30 links</u>	<u>16 links</u>

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1900 By H. Dunaway, COE
Location filed: Leech Lake Reservoir Map
Monument:
Map indicates a known corner.

Evidence of Subsequent Corner Restoration

Year of search 6/1930 By H.D. Craig, US Surveyor
Location filed: Resurvey Notes, MN Historical Soc. T144N R30W
Monument: Set 1"x36" iron pipe with brass cap up 6", at proportionate distance and marked new witnesses as follows. S10 | S11
S15 | S14
1930

Bearing Trees, Reference Objects

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Bearing Trees, Reference Objects

Species	<u>Poplar</u>	<u>Spruce</u>	<u>Poplar</u>	<u>Poplar</u>
Diameter	<u>10"</u>	<u>10"</u>	<u>6"</u>	<u>8"</u>
Bearing	<u>N 15 1/2° E</u>	<u>S 26 1/4° E</u>	<u>S 65 1/2° W</u>	<u>N 70 1/2° W</u>
Distance	<u>18 links</u>	<u>68 links</u>	<u>11 links</u>	<u>44 links</u>

Subsequent Corner Restoration

Year surveyed 10/1934 By D.J. Sutton, Compassman CCC
Location filed: Form 874-9
Monument: Found 2" brass capped pipe up 6" in good condition, placed a Metal location poster on the SW BT and notes witnesses as follows.
14" White Pine, S 32° E, 67 links(44.22') (1930)
14" Aspen, N 14 3/4° E, 18 links(11.88') (1930)
10" Aspen, N 72 1/4° W, 43 links(28.38') (1930)
8" Aspen, S 66° W, 11 links(7.26') (1930) Poster

Evidence of Subsequent Corner Restoration Found

Year of search 2/1984 By G. Brama, USFS
Location filed: USFS Book 1, page 43
Monument: Found GLO iron pipe with brass cap marked new witnesses as follows.
7" Ash, N 6° W, 36.1' nail, scribed
8" Ash, N 35° E, 12.6' nail, scribed
4" Ash, S 51° W, 28.24' nail, scribed "X"


12/1975, C.R. Krause, USFS
USFS Book 1, page 43
Found GLO 2" iron pipe with brass cap, up 18", leaning, in lowland swale and witnesses as follows.
18" Aspen, N 16° E, 11.9'(1930) scribe overgrown
21" Spruce, S 26° E, 44.9' (1930) scribe overgrown
Aspen stump, S 66° W, 7.3' (1930) log frozen to ground
16" Aspen, N 71° W, 29.0' (1930) scribe overgrown

3/1981, G. Brama, USFS
USFS Book 1, page 43
Found GLO brass cap, up 18", leaning, straighten, witnesses.
19" Poplar, N 16° E, 11.9'(1930) cut to 5' stump
22" Spruce, S 26° E, 44.9' (1930)
10" Ash, N 4° W, 9.0' (1975) FSLP

Index No. J17

CASS COUNTY LAND CORNER RECORD

T. 144 R. 30 M. 574 Coordinates: X _____ Y _____
NE 15 Corner common to sections 10, 11, 14, 15



EXISTING SURVEYS

Original Government Survey

Year surveyed 1875
Original monument Post

Species	Bearing	Trees	Distance
<u>White</u>	<u>AS 70° N</u>	<u>Maple</u>	<u>5</u>
<u>8"</u>	<u>8"</u>	<u>30 E</u>	<u>5"</u>
<u>N 42° E</u>	<u>N 60° W</u>	<u>30 E</u>	<u>558 W</u>
<u>27 LKS</u>	<u>10 LKS</u>	<u>30 LKS</u>	<u>16 LKS</u>

Original Evidence Found

Year of search _____ By _____
Monument found _____

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1930 By GLO
Location filed Sec. of State
Monument Set 1x36" W.P. Wildgrass cap T144N R30W
510 | 511
513 | 514
1930

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
<u>Poplar</u>	<u>10"</u>	<u>N 15 1/2° E</u>	<u>18 LKS</u>
<u>Spruce</u>	<u>10"</u>	<u>S 25 1/4° E</u>	<u>68 LKS</u>
<u>Poplar</u>	<u>6"</u>	<u>S 65 1/2° W</u>	<u>11 LKS</u>
<u>Poplar</u>	<u>8"</u>	<u>N 70 1/2° W</u>	<u>44 LKS</u>

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - Gary Stevenson - 1982
Doc. # 264952
Found GLO monument in good condition
7" Ash N 60° W 36.1';
4" Ash S 51° W 28.24';
8" Ash N 35° E 18.6';
21" Spruce S 26° E 44.9' (1930 BT).

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____