

T. 144 R. 30 M. 5th Coordinates: X _____ Y _____
NE 17 Corner common to sections 8, 9, 16, 17



EXISTING SURVEYS

Original Government Survey

Year surveyed 1875
Original monument Post

Original Evidence Found

Year of search _____ by _____
Monument found _____

Bearing Trees

Species	Norway Pine	Aspen	White Birch	Aspen
Diameter	28"	3"	3"	3"
Bearing	S 85° E	S 50° W	N 20° W	N 31° E
Distance	12 links	28 links	27 links	

Original Bearing Trees Found

Species				
Diameter				
Bearing				
Distance				

Subsequent Corner Restoration

Year surveyed 7/1930 By H.D. Craig, US Surveyor
Location filed: Minn. Hist. Society, notes T144N R30W
Monument: Set 6"x26" concrete with brass cap at proportionate position and marked new witnesses trees as follows.
S8 | S9
S17 | S16
1930

Evidence of Subsequent Corner Restoration

Year of search 9/1934 By D.B. Rose, Compassman CCC
Location filed: Form 874-9
Monument: Found brass cap in cement up 2" in good condition, W. of Cuba Hill Truck Rd., placed a metal location poster on the NE BT and notes witnesses as follow.

Bearing Trees, Reference Objects

Species	Poplar	Poplar	Birch	Birch
Diameter	5"	8"	5"	5"
Bearing	N 42° E	S 23° E	S 50° W	N 24° W
Distance	5 1/2 links	19 links	38 links	51 links

Bearing Trees, Reference Objects

Species	White Birch	White Birch	Aspen	Aspen
Diameter	5"(1930)	4"(1930)	4"(1930)	8"
Bearing	S 50 1/2° W	N 23 1/4° W	N 43° E	S 72°30' E
Distance	37 3/4 links	50 1/2 links	5 1/2 links	18 1/2 links

Subsequent Corner Restoration

Year surveyed 10/1974 By C.R. Krause, USFS
Location filed: USFS Book 1, page 28
Monument: Found GLO brass capped concrete monument up 4" in good condition, 290' W. of Cuba Rd. and witnesses.
Birch stump, S 50° W, 25.1'(1930) rotted
8" Birch, N 24° W, 33.7'(1930) scribe rotted out
10" White Oak, N 83° E, 36.7' scribed
8" White Oak, S 1° W, 53.7' scribed
3" Maple, N 20° W, 3.6' FSLP
12" White Oak, East, 260' FSLP
Steel Sign Post, West, 7.7' 54-4 sign


Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed: _____
Monument: _____

Index No. 59

CASS COUNTY LAND CORNER RECORD

T. 144 R. 30 M. 57A Coordinates: X _____ Y _____
NE 17 Corner common to sections 8, 9, 16, 17



EXISTING SURVEYS

Original Government Survey

Year surveyed 1875
Original monument Post

Species	Bearing	Trees
<u>N 1/2 line</u>	<u>Aspen</u>	<u>W. Birch</u>
<u>28"</u>	<u>3"</u>	<u>3"</u>
<u>S 85 E</u>	<u>S 50 W</u>	<u>N 20 W</u>
<u>12 LKS</u>	<u>28 LKS</u>	<u>27 LKS</u>

Original Evidence Found

Year of search _____ By _____
Monument found _____

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1930 By GLO
Location filed Sec. of state
Monument Set Concrete man. 26" Long 6" dia w/ brass cap
7144 N R 30 W
S 81 S 9
S 17 S 16
1930

Species	Bearing	Trees	Reference Objects
<u>Poplar</u>	<u>Poplar</u>	<u>Birch</u>	<u>Birch</u>
<u>5"</u>	<u>8"</u>	<u>5"</u>	<u>5"</u>
<u>N 42 E</u>	<u>S 23 E</u>	<u>S 50 W</u>	<u>N 23 1/4 W</u>
<u>5 1/2 LKS</u>	<u>19 LKS</u>	<u>38 LKS</u>	<u>51 LKS</u>

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - MILO STEFAN - 1974 - FILED IN 1980
Doc. # 258597
Found GLO monument in good condition
10" W. OAK N 83 E 36.70'
8" W. OAK S 1 W 53.70'

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____