


T. 144 R. 30 M. 5th Coordinates: X _____ Y _____

N 1/4 22 Corner common to sections 15, 22



EXISTING SURVEYS

Original Government Survey

Year surveyed 1875
Original monument Post

Original Evidence Found

Year of search _____ by _____
Monument found _____

Bearing Trees

Species No ties are noted
Diameter _____
Bearing _____
Distance _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed 6/1930 By H.D. Craig, US Surveyor
Location filed: Minn. Hist. Society, notes pg 103
Monument: Set 1"x 36" iron pipe with brass cap up 6", at proportionate distance and marked new witnesses as follows.

1/4 S15
S22
1930

Evidence of Subsequent Corner Restoration

Year of search 10/1934 By D.J. Sutton, Compassman CCC
Location filed: Form 874-9
Monument: Found brass capped iron pipe up 6", in good condition, placed a Metal location poster on the NW BT and notes witnesses as follows.

Bearing Trees, Reference Objects

Species Poplar Poplar
Diameter 7" 5"
Bearing S 3 1/2° W N 23 1/2° W
Distance 50 links 13 links

Bearing Trees, Reference Objects

Species Aspen Aspen
Diameter 7" 5"
Bearing S 3° W N 23°15' W
Distance 50 links 13 links

Subsequent Corner Restoration

Year surveyed 11/1966 By J. Ekstrom, USFS
Location filed: USFS Book 1, page 11
Monument: Found 1" brass capped pipe rotted stumps at 1930 witnesses, new witnesses as follow.
11" Balsam, N 38° W, 39.7' scribed 1/4 S15 BT
9" Aspen, N 30° E, 17.9' scribed 1/4 S15 BT
7" Aspen, S 76° E, 17.7' scribed 1/4 S22 BT


Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed: _____
Monument: _____

Index No. N15

CASS COUNTY LAND CORNER RECORD

T. 144 R. 30 M. 5TH Coordinates: X _____ Y _____
N1/4 22 Corner common to sections 15, 22



EXISTING SURVEYS

Original Government Survey

Year surveyed 1875
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1930 By GLO
Location filed Sec. 6 of State
Monument Set 1x36" 1/2" brass cap 4 515
4 522
1930

Evidence of Subsequent Corner Restoration

Year of search 1966 By William Okerman
Found GLO monument in good condition

Bearing Trees, Reference Objects

Species	<u>Poplar</u>	<u>Poplar</u>	_____
Diameter	<u>7"</u>	<u>5"</u>	_____
Bearing	<u>S 3 1/2 W</u>	<u>N 23 1/2 W</u>	_____
Distance	<u>50 LKS</u>	<u>13 LKS</u>	_____

Bearing Trees, Reference Objects

Balsam	Aspen	Aspen	_____
<u>11"</u>	<u>9"</u>	<u>7"</u>	_____
<u>N 38 W</u>	<u>N 30 E</u>	<u>S 76 E</u>	_____
<u>39.70'</u>	<u>17.90'</u>	<u>17.70'</u>	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - BILL OKERMAN - 1966

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____