


T. 144 R. 30 M. 5th Coordinates: X _____ Y _____

N 1/4 20 Corner common to sections 17, 20



EXISTING SURVEYS

Original Government Survey

Year surveyed 1875
Original monument Post

Original Evidence Found

Year of search _____ by _____
Monument found _____

Bearing Trees

Species	<u>Aspen</u>	<u>White Birch</u>
Diameter	<u>12"</u>	<u>10"</u>
Bearing	<u>N 8° W</u>	<u>S 8° E</u>
Distance	<u>100 links</u>	<u>78 links</u>

Original Bearing Trees Found

Species	_____	_____
Diameter	_____	_____
Bearing	_____	_____
Distance	_____	_____

Subsequent Corner Restoration

Year surveyed 7/1930 By H.D. Craig, US Surveyor
 Location filed: Minn. Hist. Society, notes 1/4 S17
 Monument: Set 1"x36" iron pipe with brass cap S20
up 6", at proportionate position and marked 1930
new witnesses as follows.

Evidence of Subsequent Corner Restoration

Year of search 9/1934 By D.J. Sutton, Compassman CCC
 Location filed: Form 874-9
 Monument: Found 1" brass capped pipe
up 5" in good condition, placed a metal location poster on the
NW witness tree and notes witnesses as follow.

Bearing Trees, Reference Objects

Species	<u>Elm</u>	<u>Maple</u>
Diameter	<u>7"</u>	<u>7"</u>
Bearing	<u>S 4 1/2° W</u>	<u>N 61° W</u>
Distance	<u>50 links</u>	<u>35 links</u>

Bearing Trees, Reference Objects

Species	<u>Elm</u>	<u>Hard Maple</u>
Diameter	<u>7"(1930)</u>	<u>7"</u>
Bearing	<u>S 5° W</u>	<u>N 61° W</u>
Distance	<u>50 1/4 links</u>	<u>34 1/4 links</u>

Subsequent Corner Restoration

Year surveyed 3/1992 By G. Brama, USFS
 Location filed: USFS Book 1, page 22
 Monument: Found GLO iron pipe with brass cap
up 3", 2643' from corner W. and witnesses as follow.
10" Elm snag, S 4° W, 33.1'(1930) scribe visible
12" Maple, N 61° W, 23.25'(1930) 60d spike
16" White Oak, N 24° W, 99.31' scribed, 60d spike
10" Maple, N 80° E, 32.33' scribed, 60d spike
3" Maple, S 32° W, 10.0' FSLP


Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
 Location filed: _____
 Monument: _____

Index No. N7

CASS COUNTY LAND CORNER RECORD

T. 144 R. 30 M. 5TH Coordinates: X _____ Y _____
N14 20 Corner common to sections 17, 20



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1875
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species Aspen W. BIRCH
Diameter 12" 10"
Bearing N8W S8E
Distance 100 LKS 70 LKS

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed 1930 By GLO
Location filed Sec of State
Monument Set 1X36" l.p. brass cap 11 517
4 520
1930

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species Elm Maple
Diameter 7" 7"
Bearing S4 1/2 W N61W
Distance 50 LKS 35 LKS

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____