


Index No. P.0-15.0

CASS COUNTY LAND CORNER RECORD

T. 144 R. 30 M. 5th Coordinates: X _____ Y _____

C 1/4 Corner common to sections 22



EXISTING SURVEYS

Original Government Survey

Year surveyed 6/1930, H.D. Craig, US Surveyor C 1/4 S 22
Original monument Set 1"x 36" iron pipe/brass cap 1930

Original Evidence Found

Year of search _____ by _____
Monument found _____

Bearing Trees

Species	<u>Poplar</u>	<u>Spruce</u>	_____
Diameter	<u>12"</u>	<u>8"</u>	_____
Bearing	<u>S 35 1/2° E</u>	<u>S 16 3/4° W</u>	_____
Distance	<u>43 links</u>	<u>32 links</u>	_____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1963 By Gamache, USFS
Location filed: USFS Book 1, page 74, 5680-11
Monument: Found corner

Evidence of Subsequent Corner Restoration

Year of search 6/1991 By G. Brama, USFS
Location filed: USFS Book 1, page 74
Monument: Found GLO iron pipe with brass cap up 14" in good condition, in Ash and Willow lowland and witnesses as follow.
Aspen stump, S 35 1/2° E, 28.4'(1930) and log

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Bearing Trees, Reference Objects

Species	<u>Spruce Stump</u>	<u>Ash</u>	<u>Ash</u>	<u>Ash</u>
Diameter	<u>(1930)</u>	<u>5"</u>	<u>8"</u>	<u>8"</u>
Bearing	<u>S 17° W</u>	<u>S 87° W</u>	<u>N 75° E</u>	<u>S 4° W</u>
Distance	<u>21.1'</u>	<u>49.75'</u>	<u>43.05'</u>	<u>38.65'</u>

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed: _____
Monument: _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed: _____
Monument: _____

