


T. 144 R. 30 M. 5th Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
E 1/4 19 Corner common to sections 19, 20



EXISTING SURVEYS

Original Government Survey

Year surveyed 1875  
Original monument Post

Original Evidence Found

Year of search \_\_\_\_\_ by \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees

Species	<u>Sugar</u>	<u>Sugar</u>
Diameter	<u>10"</u>	<u>14"</u>
Bearing	<u>N 64° E</u>	<u>S 53° W</u>
Distance	<u>75 links</u>	<u>71 links</u>

Original Bearing Trees Found

Species	_____	_____
Diameter	_____	_____
Bearing	_____	_____
Distance	_____	_____

Subsequent Corner Restoration

Year surveyed 7/1930 By H.D. Craig, US Surveyor  
Location filed: Minn. Hist. Society, notes  
Monument: Set 1"x 36" iron pipe with brass cap 1/4  
up 6", at proportionate distance and marked S19 | S20  
new witnesses as follows. 1930

Evidence of Subsequent Corner Restoration

Year of search 8/1934 By D.J. Sutton, Compassman CCC  
Location filed: Form 874-9  
Monument: Found brass cap 1" iron pipe  
up 7" in good condition, placed a metal location poster on the  
SW BT and notes witnesses as follow.

Bearing Trees, Reference Objects

Species	<u>Birch</u>	<u>Maple</u>
Diameter	<u>16"</u>	<u>6"</u>
Bearing	<u>N 13 1/4° E</u>	<u>S 71 3/4° W</u>
Distance	<u>59 links</u>	<u>29 links</u>

Bearing Trees, Reference Objects

Species	<u>White Birch</u>	<u>Red Oak</u>
Diameter	<u>16"(1930)</u>	<u>6"(1930)</u>
Bearing	<u>N 17°45' E</u>	<u>S 72°15' W</u>
Distance	<u>56 links</u>	<u>29 links</u>

Subsequent Corner Restoration

Year surveyed 10/1956 By USFS  
Location filed: USFS Book 1, page 21  
Monument: Found corner  
10" Aspen, S 58° E, 12.0' FSLP  
  
10/1974, C.R. Krause, USFS  
USFS Book 1, page 21  
Found iron pipe with brass cap up 10" in good condition, 15' N.  
of trail, 600'+/-, E. of FW #47 and witnesses as follows.  
11" Red Oak, S 72° W, 19.1'(1930) scribe overgrown  
Birch stump, N 13° E, 39.9'(1930) rotted stump  
15" Aspen, S 58° E, 12.0'(1956) found FSLP  
16" White Oak, N 45° E, 77.9' scribed 1/4 S20 Bt  
13" Maple, N 68° W, 95.5' scribed 1/4 S19 Bt  
13" Red Oak, S 26° E, 99.8' scribed 1/4 S20 Bt  
Steel Sign Post, North, 3.2' 54-4 sign  
12" Maple, N 5° W, 23.0' FSLP  
3" Maple Post, South, 1.5'

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Location filed: \_\_\_\_\_  
Monument: \_\_\_\_\_

