


Index No. P-Q 24

CASS COUNTY LAND CORNER RECORD

T. 144 R. 30 M. 5TH Coordinates: X 24 Y \_\_\_\_\_  
SMC ON Corner common to sections \_\_\_\_\_  
E 1/16 Line



EXISTING SURVEYS

Original Government Survey

Year surveyed 1930

Original monument 1 X 3/16" I.P. w brass  
cap

Species Maple Maple Bearing Trees \_\_\_\_\_  
Diameter 10" 20" \_\_\_\_\_  
Bearing N 86 1/4 E N 46 1/4 W \_\_\_\_\_  
Distance 55 LKS 100 LKS \_\_\_\_\_

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Original Bearing Trees Found

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Bearing Trees, Reference Objects

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_

Bearing Trees, Reference Objects

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

Remuneration certificate prepared \_\_\_\_\_  
By \_\_\_\_\_ Date \_\_\_\_\_ Filed at \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_  
Location filed \_\_\_\_\_  
By \_\_\_\_\_ Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_  
By \_\_\_\_\_