


T. 144 R. 30 M. 5th Coordinates: X _____ Y _____
NE 29 Corner common to sections 20, 21, 28, 29



EXISTING SURVEYS

Original Government Survey

Year surveyed 1875
 Original monument Post

Original Evidence Found

Year of search _____ by _____
 Monument found _____

Bearing Trees

Species	Spruce	Spruce	Spruce	White Birch
Diameter	8"	3"	4"	6"
Bearing	N 41° E	S 53° E	S 35° W	N 50° W
Distance	3 links	4 links	6 links	6 links

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 6/1930 By H.D. Craig, US Surveyor
 Location filed: Minn. Hist. Society, notes pg 117 T144N R30W
 Monument: Set 2"x 6" iron pipe with brass cap up 6", at proportionate position and marked new witnesses trees as follows. S20 | S21
S29 | S28
1930

Evidence of Subsequent Corner Restoration

Year of search 9/1934 By D.J. Sutton, CCC compassman
 Location filed: Form 874-9
 Monument: Found 2" iron with brass cap up 5", in good condition, placed metal location poster on the SE witness tree and notes the following.

Bearing Trees, Reference Objects

Species	Spruce	White Pine	Birch	White Pine
Diameter	14"	24"	5"	24"
Bearing	N 7 1/2° E	S 82° E	S 16 1/2° W	N 56 1/4° W
Distance	71 links	30 links	28 links	104 links

Bearing Trees, Reference Objects

Species	White Spruce	White Pine	White Birch	White Pine
Diameter	15"(1930)	20"(1930)	4"(1930)	30"(1930)
Bearing	N 8°15' E	N 55°45' W	S 16°45' W	S 82°15' E
Distance	70 links	102 links	27 3/4 links	28 links

Subsequent Corner Restoration

Year surveyed 4/1975 By C.R. Krause, USFS
 Location filed: USFS Book 1, page 24
 Monument: Found 2" brass capped iron up 4" in good condition, 1040'+/-, W. of Cuba Hill Rd and 1500' N. of woods road, notes witnesses as follow.
35" White Pine, S 82° E, 19.8'(1930) scribe overgrown
36" White Pine stump, N 56° W, 68.6'(1930) BT visible
27" White Pine, N 3° E, 70.9' scribed
26" White Pine, N 30° W, 78.4' scribed
8" Ash, S 30° W, 100.2' scribed
11" Ash, S 68° E, 58.5' scribed
Steel Sign Post, West, 2.5' 54-4 sign
20" Elm, N 88° E, 1048' FSLP


Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
 Location filed: _____
 Monument: _____

Index No. R 9

CASS COUNTY LAND CORNER RECORD

T. 144 R. 30 M. 574 Coordinates: X _____ Y _____
NE 29 Corner common to sections 20, 21, 28, 29



EXISTING SURVEYS

Original Government Survey

Year surveyed 1875
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

		Bearing Trees	
Species	<u>Spruce</u>	<u>Spruce</u>	<u>W. Birch</u>
Diameter	<u>8"</u>	<u>3"</u>	<u>6"</u>
Bearing	<u>N41E</u>	<u>S53E</u>	<u>N50W</u>
Distance	<u>3LKS</u>	<u>4LKS</u>	<u>6LKS</u>

		Original Bearing Trees Found	
Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1930 By GLO
Location filed Sec. of State
Monument Set 2x36" 1/8" w/ brass cap 7144NRW
S20/S21
S29/S28
1930

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species	<u>Spruce</u>	<u>Willow</u>	<u>Birch</u>	<u>Willow</u>
Diameter	<u>14"</u>	<u>24"</u>	<u>5"</u>	<u>24"</u>
Bearing	<u>N71/2E</u>	<u>S82E</u>	<u>S16 1/2 W</u>	<u>N56 1/4 W</u>
Distance	<u>71LKS</u>	<u>30LKS</u>	<u>28LKS</u>	<u>104LKS</u>

Bearing Trees, Reference Objects

_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - MILO STEFAN - 1975 - FILED IN 1980
Dwg. # 258586
Found GLO monument in good condition
27" W. Pine N3E 70.90';
26" W. Pine N30W 78.40';
8" Ash S30W 100.80';
11" Ash S68E 58.50'

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____