


T. 144 R. 30 M. 5th Coordinates: X _____ Y _____
N 1/16 Corner common to sections 29, 30



EXISTING SURVEYS

Original Government Survey

Year surveyed 5/1930, H.D. Craig, US Surveyor N1/16
Original monuments Set 1"x 36" iron pipe w/brass cap S30|S29
1930

Original Evidence Found

Year of search 1934 by CCC
Monument found GLO iron
Form 874-9

Bearing Trees

Species Maple Maple
Diameter 10" 8"
Bearing N 38 1/2° E N 71 1/2° W
Distance 24 links 55 links

Original Bearing Trees Found

Species Hard Maple Hard Maple
Diameter 8"(1930) 6"(1930)
Bearing N 40°45' E N 72°45' W
Distance 23 links 53 links

Subsequent Corner Restoration

Year surveyed 8/1934 By D.B. Rose, Compassman, CCC
Location filed: Form 874-9
Monument: Found 1" iron with brass cap up 10", in good condition and GLO witnesses.

Evidence of Subsequent Corner Restoration

Year of search 3/1975 By C.R. Krause, USFS
Location filed: USFS Book 2, page 8
Monument: Found iron with cap up 8", in good condition and witnesses as follow.
15" Maple, N 39° E, 15.8'(1930) scribe visible
12" Maple, N 72° W, 36.3'(1930) scribe visible
Steel Sign Post, West, 3.2' 54.2 sign

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Species Basswood White Spruce Basswood Steel Sign
Diameter 7" 15" 12" Post
Bearing N 28° E S 78° W N 75° W S 4° E
Distance 36.4' 67.4' 11.5' 3.6'

Subsequent Corner Restoration

Year surveyed 3/1981 By G. Brama, USFS
Location filed: Certificate of Location
Monument: Found GLO brass cap in good condition, W. Spruce witness is tipped over, adds. 6" Ash, East, 78.89'

Evidence of Subsequent Corner Restoration Found


Year of search _____ By _____
Location filed: _____
Monument: _____

9/1982, G.H. Stevenson, LS 12684
Certificate of Location
Found GLO monument and lists witnesses as follows.
15" Maple, N 39° E, 15.8'(1930)
12" Maple, N 72° W, 36.3'(1930)
14" Basswood, N 75° W, 11.5'(1975)
10" Basswood, N 28° E, 36.4'(1975)
6" Ash, East, 78.89'(1981)

Index No. 55

CASS COUNTY LAND CORNER RECORD

T. 144 R. 30 M. 5TH Coordinates: X _____ Y _____
N 1/16 Corner common to sections 29, 30



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1930
Original monument 1x36" L.P. witness
140

N 1/16
S 30/529
1930

Original Evidence Found

Year of search _____ By _____
Monument found _____

Species	Bearing	Trees
<u>Maple</u>	<u>10"</u>	<u>Maple</u>
<u>8"</u>	<u>N 38 1/2 E</u>	<u>N 71 1/2 W</u>
<u>24 LKS</u>	<u>55 LKS</u>	

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - Gary Stevenson - 1982
Doc. # 264954
Found GLO monument and BT's in good condition.
14" Basswood N 75 W 11.5';
10" Basswood N 88 E 36.4';
6" Ash East 78.89'

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____