


T. 144 R. 30 M. 51A Coordinates: X _____ Y _____

Cor of lots Corner common to sections
4, 5, 8, 9 and cor of tracts 388, 417, 418, 794



o = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1930 TR417 | TR 388
 Original monument 1x36" 1/2" w/bress AP4 | AP3
 cap TR 794 | TR 418

Bearing Trees 530
1930

Species _____
 Diameter _____
 Bearing _____
 Distance _____

Original Evidence Found

Year of search _____ By _____
 Monument found _____

Original Bearing Trees Found

Species _____
 Diameter _____
 Bearing _____
 Distance _____

Subsequent Corner Restoration

Year surveyed 1982 By Gary Stevenson
 Location filed Corner Certificate
 Monument in 1981 USFS End Dress cap monument
in 1982 USFS ran line from C 1/4 Sec 30 to
this corner and south to NE Cor. Lot 10
Bearings check good.

Bearing Trees, Reference Objects

Species	<u>Ash</u>	<u>Br. oak</u>	<u>w. oak</u>
Diameter	<u>10"</u>	<u>18"</u>	<u>10"</u>
Bearing	<u>N73E</u>	<u>S22E</u>	<u>S84W</u>
Distance	<u>18.18'</u>	<u>80.13'</u>	<u>14.03'</u>

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
 Location filed _____
 Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Certificate - Gary Stevenson - Filed by USFS
Dca. # 279380 1984 - dated 1982