


T. 144 R. 30 M. 5th Coordinates: X _____ Y _____
E 1/4 28 Corner common to sections 27, 28



EXISTING SURVEYS

Original Government Survey

Year surveyed 1875
Original monument Post

Original Evidence Found

Year of search 1900 by COE
Monument found _____

Leech Lake Reservoir Map

Bearing Trees

Species	<u>Spruce</u>	<u>Spruce</u>
Diameter	<u>10"</u>	<u>6"</u>
Bearing	<u>S 25° E</u>	<u>N 34° E</u>
Distance	<u>13 links</u>	<u>8 links</u>

Original Bearing Trees Found

Species	_____	_____
Diameter	_____	_____
Bearing	_____	_____
Distance	_____	_____

Subsequent Corner Restoration

Year surveyed 1900 By H. Dunaway, COE
Location filed: Leech Lake Reservoir Map
Monument:
Map indicates a known corner.

Evidence of Subsequent Corner Restoration

Year of search 6/1930 By H.D. Craig, US Surveyor
Location filed: Resurvey Notes, MN Historical Soc.
Monument: Set 1"x 36" iron pipe with brass cap up 6", at proportionate distance and marked new witnesses as follows. 1/4 S28 | S27 1930

Bearing Trees, Reference Objects

Species	_____	_____
Diameter	_____	_____
Bearing	_____	_____
Distance	_____	_____

Bearing Trees, Reference Objects

Species	<u>Birch</u>	<u>Birch</u>
Diameter	<u>7"</u>	<u>6"</u>
Bearing	<u>S 49 1/4° E</u>	<u>S 9 3/4° W</u>
Distance	<u>63 links</u>	<u>28 links</u>

Subsequent Corner Restoration

Year surveyed 10/1934 By F.E. Sandberg, Forman, CCC
Location filed: Form 874-9
Monument: Found brass capped pipe up 6" in good condition and notes witnesses as follows.
7" Birch, S 34° W, 67 links(44.22')
6" Birch, S 19°20' E, 43 links(28.38')

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed: _____
Monument: _____

3/1975, C.R. Krause, USFS
USFS Book 1, page 46
Found GLO 1" iron pipe with brass cap, up 10", in good condition, in small Ash lowland and witnesses as follows.
12" Birch, S 49° E, 41.6'(1930) scribe visible
13" Birch, S 10° W, 18.5' (1930) scribe visible
12" White Pine, S 86° W, 40.0' marked 1/4 S28 BT
8" Elm, S 12° E, 31.4' marked 1/4 S27 BT
7" Ash, N 47° W, 34.9' marked 1/4 S28 BT
Steel Sign Post, North 2.0' 54-4 sign
4" Cedar Post, South, 265' FSLP, N. side Cuba Hill Rd.

