


T. 144 R. 30 M. 5th Coordinates: X _____ Y _____
C.W. 1/16 Corner common to sections 27



EXISTING SURVEYS

Original Government Survey

Year surveyed 6/1930, H.D. Craig, US Surveyor W 1/16
Original monument Set 1"x 36" iron pipe w/brass cap C-S27-C
1930

Original Evidence Found

Year of search _____ by _____
Monument found _____

Bearing Trees

Species	<u>Elm</u>	<u>Ash</u>	_____	_____
Diameter	<u>12"</u>	<u>6"</u>	_____	_____
Bearing	<u>N 16° E</u>	<u>S 62 1/4° W</u>	_____	_____
Distance	<u>57 links</u>	<u>53 links</u>	_____	_____

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 2/1975 By C.R. Krause, USFS
Location filed: USFS Book 1, page 47
Monument: Found iron pipe with brass cap up 8" in good condition, in grass slough, 350' N. of Cuba Hill Rd. and the following witnesses.
18" Elm, N 16° E, 37.6'(1930) scribe overgrown
10" Ash, S 62° W, 35.0'(1930) scribe overgrown

Evidence of Subsequent Corner Restoration

Year of search _____ By _____
Location filed: _____
Monument: _____

Bearing Trees, Reference Objects

Species	<u>Ash</u>	<u>Cedar</u>	<u>Steel Sign</u>	<u>Steel Sign</u>
Diameter	<u>12"</u>	<u>11"</u>	<u>Post</u>	<u>Post</u>
Bearing	<u>S 18° W</u>	<u>West</u>	<u>North</u>	<u>East</u>
Distance	<u>37.1'</u>	<u>74.8'</u>	<u>3.5'</u>	<u>5.2'</u>

Bearing Trees, Reference Objects

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed: _____
Monument: _____


Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed: _____
Monument: _____

Index No. T14

CASS COUNTY LAND CORNER RECORD

T. 144 R. 30 M. 5TH Coordinates: X _____ Y _____
C. W. 116 Corner common to sections 27



EXISTING SURVEYS

Original Government Survey

Year surveyed 1930
Original monument 1x36" 1.P. w/brass cap

W 116
C 527 C
1930

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees
Species Elm Ash _____
Diameter 12" 6" _____
Bearing N16E S62 1/4 W _____
Distance 57 LKS 53 LKS _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

○ = Corner

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - MILO STEFAN - 1975 FILED IN 1980
Doc. # 258585
Found GLO monument in good condition
12" Ash S18W 37.10'
11" Cedar West 74.80'

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____