


T. 144 R. 30 M. 5th Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
E 1/4 27 Corner common to sections 26, 27



27

● = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1875  
Original monument Post

Original Evidence Found

Year of search \_\_\_\_\_ by \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees

Species	<u>Ash</u>	<u>Ash</u>
Diameter	<u>6"</u>	<u>3"</u>
Bearing	<u>S 24° E</u>	<u>S 57° E</u>
Distance	<u>25 links</u>	<u>20 links</u>

Original Bearing Trees Found

Species	_____	_____
Diameter	_____	_____
Bearing	_____	_____
Distance	_____	_____

Subsequent Corner Restoration

Year surveyed 6/1930 By H.D. Craig, US Surveyor  
Location filed: Minn. Hist. Society, notes  
Monument: Set 1"x 36" iron pipe with brass cap up 6", at proportionate position and marked new witnesses as follows. 1/4 S27 | S26 1930

Evidence of Subsequent Corner Restoration

Year of search 11/1934 By P. Zeleagraff, Estimator CCC  
Location filed: Form 874-9  
Monument: Found iron pipe Brass cap and notes witnesses as follow.

Bearing Trees, Reference Objects

Species	<u>Cedar</u>	<u>Cedar</u>
Diameter	<u>7"</u>	<u>10"</u>
Bearing	<u>N 14° E</u>	<u>N 68 1/2° W</u>
Distance	<u>70 links</u>	<u>72 links</u>

Bearing Trees, Reference Objects

Species	<u>Cedar</u>	<u>Cedar</u>
Diameter	<u>10"(1930)</u>	<u>6"(1930)</u>
Bearing	<u>N 76° W</u>	<u>N 7° E</u>
Distance	<u>51'</u>	<u>51'</u>

Subsequent Corner Restoration

Year surveyed 2/1975 By C.R. Krause, USFS  
Location filed: USFS Book 1, page 49  
Monument: Found iron without cap in center of Cuba Hill Rd. and witnesses as follows.  
10" Cedar, N 14° E, 46.2'(1930) scribe visible  
20" Cedar, N 69° W, 47.5'(1930) scribe closed

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Location filed: \_\_\_\_\_  
Monument: \_\_\_\_\_

5/1986, C.R. Krause, USFS  
USFS Book 1, page 49  
Found GLO iron, no cap, bent, remove prior to Rd. Const. place mag pellet in hole and witnesses as follow.  
10" Cedar, N 14° E, 46.2'(1930) scribe visible  
20" Cedar, N 69° W, 47.5'(1930) scribe closed  
18" White Pine, S 14° W, 31.65' spike and tag  
15" Maple, N 15° W, 73.3' spike and tag

8/1990, C.R. Krause, USFS  
USFS Book 1, page 49  
Set USFS 2" iron pipe with brass cap place GLO pipe adjacent on S. side, down 8" in center of Cuba Hill Rd. The NW 1930 Cedar witness is gone, all other witnesses are in good condition. T144N R30W 1/4 S27 | S26 1990 USFS

