


T. 144 R. 30 M. 5th Coordinates: X _____ Y _____
E 1/4 30 Corner common to sections 29, 30



EXISTING SURVEYS

Original Government Survey

Year surveyed 1875
Original monument Post

Original Evidence Found

Year of search 1930 by Craig
Monument found _____
Minn. Hist. Society, notes

Bearing Trees

Species Spruce White Pine
Diameter 12" 20"
Bearing S 67° E N 83° W
Distance 27 links 54 links

Original Bearing Trees Found

Species White Pine
Diameter 24" Dead
Bearing N 83° W
Distance 54 links

Subsequent Corner Restoration

Year surveyed 6/1930 By H.D. Craig, US Surveyor
Location filed: Minn. Hist. Society, notes
Monument: Set 1"x 36" iron pipe with brass cap 1/4
from remains of GLO witness and marked new S30 | S29
witnesses as follows. 1930

Evidence of Subsequent Corner Restoration

Year of search 3/1975 By C.R. Krause, USFS
Location filed: USFS Book 2, page 7
Monument: Found iron and cap
up 5" in good condition, 230' W. of woods Rd., rotted and
burned stump at original witness location and notes witnesses
as follow.

Bearing Trees, Reference Objects

Species Burr Oak Oak
Diameter 14" 16"
Bearing S 61 3/4° E S 24 1/2° W
Distance 283 links 174 links

Bearing Trees, Reference Objects

Species Burr Oak Oak
Diameter 19"(1930) 19"(1930)
Bearing S 62° E S 25° W
Distance 186.78' 114.84'

Subsequent Corner Restoration

Year surveyed 3/1981 By G. Brama, USFS
Location filed: Certificate of Location
Monument: Found iron with cap
up 5" in good condition and witnesses as follows.
20" Oak, S 25° W, 114.8'(1930)
4" Ash, N 30° W, 52.02' scribed
6" Ash, S 60° E, 137.20' scribed

9/1982, G.H. Stevenson, LS 12684
Certificate of Location
Found GLO corner.

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed: _____
Monument: _____

