


Index No. V15

CASS COUNTY LAND CORNER RECORD

T. 144 R. 30 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
N/4 34 Corner common to sections 27, 34



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1875  
Original monument Post

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Species	Bearing	Trees
<u>Cedar</u>	<u>Cedar</u>	
Diameter <u>8"</u>	<u>4"</u>	
Bearing <u>N74E</u>	<u>S88E</u>	
Distance <u>202LKS</u>	<u>215LKS</u>	

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1930 By GLO  
Location filed Sec. of State  
Monument Find SE B.T. (now 10") set 1x36" 1-P.w./brass cap

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Bearing Trees, Reference Objects

Species	Bearing	Reference Objects
<u>Cedar</u>	<u>Cedar</u>	
Diameter <u>12"</u>	<u>8"</u>	
Bearing <u>S59W</u>	<u>N7W</u>	
Distance <u>17LKS</u>	<u>17LKS</u>	

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
CERTIFICATE - Gary Stevenson - 1982  
Doc. # 244962  
Found GLO monument in good condition  
12" Cedar S59W 11.22' (1930 BT);  
12" Cedar N7W 11.22' (1930 BT);  
8" Cedar S84E 8.33'

Remonumentation certificate prepared \_\_\_\_\_

By \_\_\_\_\_

Filed at \_\_\_\_\_

Date \_\_\_\_\_