


Index No. V 18

CASS COUNTY LAND CORNER RECORD

T. 144 R. 30 M. 5TH Coordinates: X _____ Y _____
W 1/16 Corner common to sections 26, 35



EXISTING SURVEYS

Original Government Survey

Year surveyed 1930

Original monument 1x36" IR. w/ brass cap W 1/16 526
535
1930

Species	Bearing	Trees
<u>Ash</u>	<u>W. oak</u>	
<u>4"</u>	<u>12"</u>	
<u>N37 1/2 E</u>	<u>S44 E</u>	
<u>37 LKS</u>	<u>91 LKS</u>	

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species	Bearing	Distance
_____	_____	_____
_____	_____	_____
_____	_____	_____
_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration

Year of search 1988 By Gary Stevenson

Corner Certificate - Doc # 303286

Find brass cap monument

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
<u>Balsam</u>	<u>9"</u>	<u>N75 E</u>	<u>17.27'</u>
<u>Ash</u>	<u>7"</u>	<u>S55 E</u>	<u>25.75'</u>
<u>Ash</u>	<u>7"</u>	<u>S25 W</u>	<u>22.69'</u>
<u>Ash</u>	<u>12"</u>	<u>N30 E</u>	<u>24.8'</u>
<u>GLOBT-Oak Stump</u>			<u>S40 E 60.3'</u>
			<u>GLO</u>

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Certificate - Gary Stevenson - 1988

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____